



U.S. Department
of Transportation
**Federal Aviation
Administration**



SDR

Summary

Service Difficulty Reporting

March 22, 1998 - March 28, 1998

GENERAL AVIATION, ZAC-327

You can improve Air Safety by reporting the problem when you see it!

SECTION

- I Significant Occurrence Report
- II Domestic Service Difficulty Report
- III International Service Difficulty Report
- IV SDR Totals by District Office
- V Index By Aircraft Make and Model
- VI Joint Aircraft System/Component Code Table

ISSUE: 98-13



U.S. Department
of Transportation
**Federal Aviation
Administration**

SDR SUMMARY

General Aviation, ZAC-327



This summary includes domestic (United States) Service Difficulty Reports (SDRs) entered into the data base for aircraft weighing 12,500 lbs. and below. It also includes reports on aeronautical products (engines, propellers, and components), and all helicopters. A separate section for International SDRs for aircraft weighing 12,500 lbs. and under has also been included. Under a data exchange agreement, International SDRs are submitted to the FAA by the Civil Aviation Authority of other countries (currently, Canada - CAN, and Australia - AUS). All reports are sorted by aircraft make, model group (basic model), and Joint Aircraft System/Component (JASC) code. Within each aircraft model group, the specific model shown may vary, but similar types of reports will be grouped together and listed in ascending order by their JASC code. Each field contains all information submitted to the FAA. Some fields are not included in order to make the summary easier to read. Additional information may be obtained by referring to the "operator control number." Send your request to the Aviation Data Systems Branch, AFS-620 at the address or phone below.

The Regulatory Support Division (AFS-600) has established a "HomePage" on the Internet through which the same information is available. There is a large quantity of other information available through the AFS-600 HomePage such as the most current SDR system codes (i.e., Joint Aircraft System/Component Codes). The SDR Question and Answer Section of the Summary will also be transferred to the AFS-600 HomePage to simplify the process of preparing the SDR Summaries in the PDF format each week. There are "hot buttons" to take you to other locations and sites where FAA Flight Standards Service Information is available. The AFS-600 "HomePage" address is:

<http://www.mmac.jccbi.gov/afs/afs600>

"The Service Difficulty Reports in this publication are derived from unverified information submitted by the aviation community without FAA verification for accuracy. The number of SDRs submitted is not an indication of the mechanical reliability or fitness of an airline or individual operator, and the information should not be used as such."

Comments are welcomed and may be directed to:


*Federal Aviation Administration
Aviation Data Systems Branch, AFS-620
P.O. Box 25082
Oklahoma City, OK 73125-5029
Phone: (405) 954-4171, Fax: (405) 954-4748*

Your continued participation is essential and is an integral part of ensuring aviation safety. Thank you for supporting the Service Difficulty Program! If you have any questions regarding this special notice you can contact John Jackson at (405) 954-6486, or Jim Gillespie at (405) 954-1141, or Blake McDonald at (405) 954-0307 in the Aviation Systems Branch (AFS-620). Their E-mail addresses are:

john_e_jackson@mmacmail.jccbi.gov

james_gillespie@mmacmail.jccbi.gov

blake_mcdonald@mmacmail.jccbi.gov



SIGNIFICANT OCCURRENCE REPORT





U.S. Department
of Transportation
**Federal Aviation
Administration**

THE SIGNIFICANT OCCURRENCE REPORT



The Significant Occurrence Report is a compilation all of the star bordered reports that appear in the General Aviation Service Difficulty Report (SDR) Summary, ZAC-327. The Significant Occurrence Report is used to highlight industry problem areas to field inspectors and the aviation public.

Limited analysis is performed by the Aviation Data Systems Branch, AFS-620 during the preparation of the "Significant Occurrence Report", which is generated each week and is included in the front of the Air Carrier SDR Summary. Significant Reports are hand selected by AFS-620's inspectors based on the individual merit of each report. The criteria for selection includes, but is not limited to, items that indicate high failure rates; items related to accidents or incidents; or design or maintenance failures which may affect the safe operation of the aircraft.

In some cases, this limited analysis of SDR data leads to the preparation of information bulletins which are routed to the appropriate product certification office for further investigation of the problem. The end result may be the issuance of an airworthiness directive (AD) by the Aircraft Certification Service (AIR) if warranted.

The Significant Occurrence Report (section I) of the weekly SDR Summary is not intended to be a summary of all significant events and should not be used as such. We recommend that you review further the applicable sections of the SDR summary that may be of interest.

GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT

3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
5740 Q2AR *****	438RJ 502A0345	AIRTRC AT502A				ANGLE	CRACKED WING ATTACH OTBD	1241	3/2/98 98ZZZX1162
DURING ANNUAL INSPECTION AND C/W WING ATTACH ANGLE BOLT INSPECTION, OUTBOARD WING ATTACHMENT ANGLE FOUND CRACKED.									
5520 *****	77412 11853	CESSNA 120				BEARING 042215	WORN ELEVATOR HINGE	4626	2/15/98 98ZZZX1137
INSPECTION FOUND INNER RACE ELEVATOR HINGE BEARING INSIDE DIAMETER WORN EXCESSIVELY. REPLACED BEARING AND BOLT.									
5753 *****	4642J 17273658	CESSNA 172N				BEARING 0523920	FAILED RT OUTER AFT	7200	1/13/98 98ZZZX1134
DURING TOUCH AND GO PRACTICE, RT FLAP OUTER AFT BEARING FAILED DURING RETRACTION. THE FAILURE CAUSED THE FLAP TO BIND AND TRIP CIRCUIT BREAKER, BUT NOT UNTIL AFTER THE RT FLAP HAD BEEN DAMAGED BY THE BINDING. THE FLAP SKINS AND SPAR WERE DAMAGED OUTBOARD OF PUSH/PULL ROD. DAMAGED ENOUGH TO WARRANT REPAIR OF FLAP. THE AIRCRAFT WAS INSPECTED PER A 100-HOUR 45 HOURS BEFORE WITH NO DEFECTS FOUND.									
5753 *****	94035 21060487	CESSNA T210L				BEARING 0523920	SEIZED FLAP ROLLER	1960	1/26/98 98ZZZX1132
DURING AN ANNUAL INSPECTION TO CHECK FLAP BEARINGS AFTER A FAILURE ON A CE-172, FOUND 10 OUT OF 12 BEARINGS WITH THE NEEDLE BEARINGS SEIZED. NO VISUAL SIGN OF WEAR. CLEANED, LUBED, REINSTALLED. SUBMITTER RECOMMENDED 1,000-HOUR INSPECTIONS REQUIRING REMOVAL.									
2140 *****	2644U 310R1811	CESSNA 310R			8259JR2	FUEL LINE	CORRODED HEATER		3/4/98 98ZZZX1120
DURING ANNUAL INSPECTION AND BY C/W AD 81-09-09 BY VISUAL INSPECTION, CORROSION WAS FOUND ON THE FORWARD FUEL INLET LINE AFT OF THE HEATER PUMP VALVE. SUBMITTER STATED THIS IS THE THIRD LINE FOUND WITH THIS PROBLEM ON THREE DIFFERENT 310R'S.									
3230 *****	5092P 310P0057	CESSNA 310P				TUBE ASSY 08421211	FAILED NLG	7451	3/9/98 98ZZZX1110
NOSE GEAR ROD END ASSY FAILED. THE BEARING WAS FREE AND NOT SEIZED.									
5700 XM8R *****	340TS 340A0999	CESSNA 340A				NACELLE 562010023	CORRODED LT WING ASSY	2095	2/16/98 98ZZZX1144
FUEL LEAKING FROM RT WING FND COMING FROM RT NACELLE FUEL CELL. REMOVED NACELLE ACCESS COVER, FUEL CELL LINER, HEAT SHIELD, AND FUEL CELL. SEVERE CORROSION FND ON UPPER WING SKIN AND STRS. FUEL CELL LINER CORRODED (EXFOLIATED). ALSO, LT NACELLE INSPECTED FOR SIMILAR CONDITION. AFTER REMOVAL OF LT NACELLE COVER AND FUEL CELL, SEVERE CORROSION FND. UPPER WING SKIN, STRINGERS AND UPPER SPAR CAP ARE ALL EXFOLIATED. AFT SIDE OF LT FIREWALL DISCOLORED FROM HEAT AND FUEL CELL HEAT SHIELD IS BURNED THROUGH. HEAT DAMAGE MAY BE CAUSED BY A PREVIOUS EXH FAILURE. ACFT IS WELL MAINTAINED, HANGARED MOST OF THE YEAR AND NOT HIGH TIME. SUBMITTER BELIEVES THIS IS A PROBLEM THAT MAY GO UNDETECTED ON SIMILAR ACFT.									
2510 *****	87144 402B0933	CESSNA 402B				BRACKET	FAILED PILOT SEAT BACK		2/25/98 98ZZZX1174
PILOT SEAT BACK RECLINED IN-FLIGHT. BRACKET ON RIGHT SIDE OF SEAT BROKEN. CASTING APPEARS TO HAVE BEEN CRACKED PRIOR TO FAILURE.									
2731 *****	PHECA 0321	CESSNA 414A				ELEV TAB	MISRIGGED ELEV TRIM	3700	3/8/98 98ZZZX1181
DURING A 1,000 HR INSP ON RUD-AIL, AND ELEV TRIM IAW CE 414 SM, REV 31, FOUND ELEV TRIM TAB TRAVEL WAS 12 DEG UP/21 DEG DOWN. CHECKED MANUAL FOR TRAVELS OF TRIM TABS AND FOUND IN MM, REV 31, RIGGINGS FOR ELEV TRIM TAB UP: 5 DEG AND DOWN: 30 DEG. DOUBLE CK MM REV HISTORY, FOUND ELEV TRIM TAB TRAVELS ALTERED WITH MM REV 31, DATED 2-3-97. (OLD TRAVELS WERE: 12 DEG UP AND 20 DEG DOWN, TOL. +1 DEG). DURING INSTALL, SET TRAVELS IAW MM REV 31: 5 DEG UP AND 30 DEG DOWN. FIRST FLIGHT (TRIM NEUTRAL) ACFT EXPERIENCED A NOSE UP AT TAKE OFF THAT COULD NOT BE CORRECTED BY TRIMMING THE ELEV; IT WAS AGAINST ITS 'NOSE DOWN' STOP, AND FORCE HAD TO BE IMPOSED UPON COLUMN TO KEEP ACFT IN LEVEL FLIGHT.									

***** DENOTES SIGNIFICANT OCCURRENCE

GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
7120 WTXR *****	441W 4410181	CESSNA 441				MOUNT 57510061	CRACKED LT ENG INBD	5039	2/12/98 98ZZZX1122
WHILE INVESTIGATING A ROUGH ENGINE, FOUND AN ENGINE MOUNT TUBE CRACKED THROUGH ON LT ENGINE INBOARD, UPPER CLUSTER, LOWER TUBE. INSTALLED DIFFERENT REPAIRED TRUSS.									
2435 *****		DHAV DHC6300	PWA PT6A27		LUCAS 23048004	BEARING 9204SSX10	UNAPPROVED START/GEN	12/18/97 987	CA971231025
(CAN) INSPECTION FOUND THAT THE BEARINGS WERE UNAPPROVED FOR THIS INSTALLATION. THE BEARING FOUND WAS MANUFACTURED BY BARDEN. ONLY LUCAS BEARINGS P/N 03-6010-18 SHOULD BE USED. THERE WAS ALSO A BRASS SHIM BETWEEN THE DRIVE SHAFT AND THE DAMPER HUB ALLOWING THE HUB TO SIT LOWER DOWN ON THE SHAFT. THIS IS ALSO AN UNAPPROVED PRACTICE. IN ADDITION, THE FRONT END BELL LINER WAS NOT REPAIRED PER APPROVED SPECS.									
2430 *****	19PV 560416	GULSTM 560				GROUND CONNECT	LOOSE START/GENERATOR	514	3/13/98 98ZZZX1169
PILOTS REPORTED A PARALLELING PROBLEM WITH THE GENERATORS. INSPECTION REVEALED BOTH STARTER/GENERATOR GROUND CONNECTIONS WERE LOOSE. MINOR ARCING WAS NOTED ON LEFT GROUND. BOTH CONNECTIONS WERE CLEANED AND RESEATED. THIS CONDITION RESULTED FROM IMPROPER TORQUE OF ATTACHING HARDWARE.									
5711 *****	600AA 2825102	PIPER PA28140				SPAR CAP	CORRODED AFT SPAR CAP	4577	3/18/98 98ZZZX1172
DURING WING INSPECTION, FOUND EVERY WHERE THAT SOUNDPROOF INSULATION COMES IN CONTACT WITH THE FERROUS AFT SPAR CAP, THAT CORROSION SETS IN DUE TO THE MOISTURE THAT THE INSULATION HOLDS.									
2140 *****	63ND 317852098	PIPER PA31350				HEATER B405065D722	FAILED FORWARD	362	3/5/98 98ZZZX1123
DURING FLIGHT, THE COCKPIT FILLED WITH A GREENISH, YELLOW SMOKE EMANATING FROM THE DEFROST AND HEATER DUCTS. PILOT SHUT DOWN THE FORWARD HEATER AND EVACUATED THE SMOKE FROM THE CABIN. THE FLIGHT CONTINUED TO THE ORIGINAL DESTINATION. THE AIRCRAFT WAS INSPECTED AND FOUND UNDAMAGED. THE FORWARD HEATER HAD OVERHEATED. WITHOUT FURTHER INSPECTION OF THE HEATERS, THE DAMAGE AND SYMPTOMS ARE CONSISTENT WITH A PERFORATED BURNER CAN. THIS COMBUSTION HEATER HAD A PRESSURE DECAY TEST IAW AD 96-20-07 ON 1-18-98, AND HAD ACCUMULATED 62.4 HEATER HOURS OF OPERATION SINCE THAT DATE.									
6710 *****	159RP 0342	ROBSIN R44			C5811	SPRING ASSY C0561	FAILED LATERAL TRIM	199	3/12/98 98ZZZX1164
WHILE PERFORMING INSPECTION FOR AD 98-06-12, FOUND LATERAL TRIM SPRING ASSY PULLED COMPLETELY OUT OF MOUNTING BLOCK AND DANGLING AGAINST BELLY SKIN. TRIM MOTOR ARM P/N C581-1 FROZEN ON SPRING SHAFT. SUBMITTER STATED HAD THIS UNIT FAILED IN-FLIGHT, LOSS OF CONTROL WOULD HAVE BEEN POSSIBLE. THE REPLACEMENT SPRING ASSY LOWER BEARING IS STAKED INTO THE MOUNTING BLOCK, YET THIS IS NOT THE CAUSE OF THE AD. SUBMITTER RECOMMENDED REVISION OF AD 98-04-12 TO REQUIRE IMMEDIATE REPLACEMENT OF AFFECTED SPRING ASSY REGARDLESS OF SHAFT WEAR.									
6710 *****	972SA 0394	ROBSIN R44				SHAFT C5851	WORN CYCLIC CONTROL	63	1/22/98 98ZZZX1115
ROTORCRAFT EXPERIENCED A PARTIAL CYCLIC CONTROL FAILURE WHILE LANDING. PILOT WAS UNABLE TO ROLL LEFT USING CYCLIC INPUT. INVESTIGATION REVEALED THAT LATERAL TRIM ACTUATOR ASSEMBLY SHAFT, PN C585-1, HAD A STEP WORN IN IT WHICH ALLOWED THE TRIM ACTUATOR TO JAM. THREE ADDITIONAL AIRCRAFT INSPECTED REVEALED THE SAME PROBLEM. LATERAL TRIM ACTUATOR ASSEMBLY WAS REPLACED ON ALL 4 AIRCRAFT. SAFETY RECOMMENDATIONS SUBMITTED. AD 98-04-12 ISSUED TO INSPECT AND CORRECT THIS PROBLEM ON ALL R44 HELICOPTERS.									

(End of GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT)

Run Date: 02-Apr-98

FEDERAL AVIATION ADMINISTRATION
SIGNIFICANT OCCURRENCE REPORT INDEX

Showing Specific Part Numbers and Aircraft Model by Year

FOR THE PERIOD OF: 3/22/98 To 3/28/98

<u>PART NUMBER</u>		<u>YEAR</u>												
<u>PART NAME</u>	<u>ACFT MODEL</u>	<u>TOTAL</u>	<u>1987</u>	<u>1988</u>	<u>1989</u>	<u>1990</u>	<u>1991</u>	<u>1992</u>	<u>1993</u>	<u>1994</u>	<u>1995</u>	<u>1996</u>	<u>1997</u>	<u>1998</u>
042215														
BEARING	120	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # 042215 -----		1	-	-	-	-	-	-	-	-	-	-	-	1
0523920														
BEARING	172N	1	-	-	-	-	-	-	-	-	-	-	-	1
	T210L	1	-	-	-	-	-	-	-	-	-	-	-	1
BUSHING	172N	1	-	-	-	-	-	-	-	-	1	-	-	-
ROLLER	172	1	-	-	-	1	-	-	-	-	-	-	-	-
	172M	1	-	-	-	1	-	-	-	-	-	-	-	-
	172N	1	-	-	-	-	-	-	-	-	-	-	1	-
	TU206G	1	-	-	-	-	-	-	-	-	1	-	-	-
ROLLER ASSY	172M	1	-	-	-	-	-	-	-	-	-	-	-	1
	172RG	1	-	-	-	-	-	-	-	-	-	1	-	-
	182C	1	-	-	-	-	-	-	1	-	-	-	-	-
TOTAL of # 0523920 -----		10	-	-	-	2	-	-	1	-	2	1	1	3
08421211														
BELLCRANK	310L	1	-	-	-	-	-	-	-	-	1	-	-	-
PUSH PULL ROD	320F	1	-	-	-	1	-	-	-	-	-	-	-	-
PUSH-PULL TUBE	310K	1	-	-	-	-	-	-	-	-	1	-	-	-
RETRACT TUBE	310Q	1	-	-	-	1	-	-	-	-	-	-	-	-

FAA SIGNIFICANT OCCURRENCE REPORT INDEX 3/22/98 To 3/28/98 (cont'd)


<u>PART NUMBER</u>		<u>YEAR</u>												
<u>PART NAME</u>	<u>ACFT MODEL</u>	<u>TOTAL</u>	<u>1987</u>	<u>1988</u>	<u>1989</u>	<u>1990</u>	<u>1991</u>	<u>1992</u>	<u>1993</u>	<u>1994</u>	<u>1995</u>	<u>1996</u>	<u>1997</u>	<u>1998</u>
08421211														
ROD ASSEMBLY	310N	1	-	-	-	-	-	1	-	-	-	-	-	-
TUBE	310Q	1	-	-	-	1	-	-	-	-	-	-	-	-
TUBE ASSY	310A	1	-	-	-	-	-	-	-	-	1	-	-	-
	310L	1	-	-	-	-	-	-	-	-	-	-	1	-
	310P	1	-	-	-	-	-	-	-	-	-	-	-	1
	310Q	1	-	-	-	-	-	-	-	1	-	-	-	-
	T310Q	1	-	-	-	-	-	-	-	1	-	-	-	-
TOTAL of # 08421211 - - - - -		11	-	-	-	3	-	1	-	2	3	-	1	1
5011002593														
SKIN	B300C	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # 5011002593 - - - - -		1	-	-	-	-	-	-	-	-	-	-	-	1
562010023														
NACELLE	340A	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # 562010023 - - - - -		1	-	-	-	-	-	-	-	-	-	-	-	1
57510061														
MOUNT	441	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # 57510061 - - - - -		1	-	-	-	-	-	-	-	-	-	-	-	1
5A26441														
RESERVOIR	747438	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # 5A26441 - - - - -		1	-	-	-	-	-	-	-	-	-	-	-	1
9204SSX10														
BEARING	DHC6300	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # 9204SSX10 - - - - -		1	-	-	-	-	-	-	-	-	-	-	-	1
B405065D722														
HEATER	PA31350	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # B405065D722 - - - - -		1	-	-	-	-	-	-	-	-	-	-	-	1
C0561														
SPRING ASSY	R44	2	-	-	-	-	-	-	-	-	-	-	1	1

FAA SIGNIFICANT OCCURRENCE REPORT INDEX 3/22/98 To 3/28/98 (cont'd)

<u>PART NUMBER</u>		<u>YEAR</u>												
<u>PART NAME</u>	<u>ACFT MODEL</u>	<u>TOTAL</u>	<u>1987</u>	<u>1988</u>	<u>1989</u>	<u>1990</u>	<u>1991</u>	<u>1992</u>	<u>1993</u>	<u>1994</u>	<u>1995</u>	<u>1996</u>	<u>1997</u>	<u>1998</u>
TOTAL of # C0561 - - - - -		2	-	-	-	-	-	-	-	-	-	-	1	1
C5851														
SHAFT	R44	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # C5851 - - - - -		1	-	-	-	-	-	-	-	-	-	-	-	1
F12A11														
BEARING	unknown	1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL of # F12A11 - - - - -		1	-	-	-	-	-	-	-	-	-	-	-	1
TOTAL for ALL (31) PART NUMBERS: - - - -		32	-	-	-	5	-	1	1	2	5	1	3	14
END OF SIGNIFICANT OCCURRENCE REPORT INDEX														



DOMESTIC SERVICE DIFFICULTY REPORT



DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT**3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
5740 Q2AR *****	438RJ 502A0345	AIRTRC AT502A				ANGLE	CRACKED WING ATTACH OTBD	1241	3/2/98 98ZZZX1162
DURING ANNUAL INSPECTION AND C/W WING ATTACH ANGLE BOLT INSPECTION, OUTBOARD WING ATTACHMENT ANGLE FOUND CRACKED.									
7603	5169X 676	BBAVIA 7ECA				CABLE 31402	FAILED THROTTLE	2487	3/3/98 98ZZZX1119
THROTTLE CABLE BROKE APPROXIMATELY 1.5 INCHES FROM THROTTLE LEVER. OLDER AIRCRAFT USED QQ-2-470 MUSIC WIRE .090 INCH DIAMETER. INNERGRANULAR CORROSION WAS NOTED IN THE BROKEN AREA. SUBMITTER RECOMMENDED CABLE BE REPLACED WITH 20253-P2 PIN MATERIAL OR UPGRADE AIRCRAFT TO LATE MODEL CABLE SYSTEM.									
2434	3058S CE1099	BEECH F33A				ALTERNATOR 646843	FAILED WINDING		3/15/97 98ZZZX1128
PILOT EXPERIENCED ELECTRICAL SYSTEM FAILURE. MADE EMERGENCY LANDING WITHOUT INCIDENT. FOUND ALTERNATOR FAILED.									
2721 TIMA	955AA UI28	BEECH 99A				NUT AN3166R	CORRODED RUD TAB ACTUATOR	28112	2/1/98 98ZZZX1171
RUDDER TAB ACTUATOR NUT FOUND CORRODED DURING ROUTINE INSPECTION.									
5520 *****	77412 11853	CESSNA 120				BEARING 042215	WORN ELEVATOR HINGE	4626	2/15/98 98ZZZX1137
INSPECTION FOUND INNER RACE ELEVATOR HINGE BEARING INSIDE DIAMETER WORN EXCESSIVELY. REPLACED BEARING AND BOLT.									
5711	77412 11853	CESSNA 120				SPAR BLOCK 0411131	CORRODED FRONT SPAR	4626	2/15/98 98ZZZX1135
BLOCK 5 (4, NR 0411129) REMOVED. CHECKED INSIDE OF FRONT AND REAR SPARS. SLIGHT CORROSION FOUND. CLEANED AND PAINTED WITH ZINC CHROMATE. MOST BOLTS FROZEN INTO BLOCKS. BOLTS HAD TO BE POUNDED OR DRILLED OUT. RECOMMEND THAT BLOCKS BE REMOVED IF WINGS ARE TAKEN OFF FOR ANY REASON TO CHECK INSIDE OF SPARS.									
5711	77412 11853	CESSNA 120				SPAR BLOCK 0411476	CORRODED REAR SPAR	4626	2/15/98 98ZZZX1136
BLOCK 5 (4, NR 0411129) REMOVED. CHECKED INSIDE OF FRONT AND REAR SPARS. SLIGHT CORROSION FOUND. CLEANED AND PAINTED WITH ZINC CHROMATE. MOST BOLTS FROZEN INTO BLOCKS. BOLTS HAD TO BE POUNDED OR DRILLED OUT. RECOMMEND THAT BLOCKS BE REMOVED IF WINGS ARE TAKEN OFF FOR ANY REASON TO CHECK INSIDE OF SPARS.									
5753 *****	4642J 17273658	CESSNA 172N				BEARING 0523920	FAILED RT OUTER AFT	7200	1/13/98 98ZZZX1134
DURING TOUCH AND GO PRACTICE, RT FLAP OUTER AFT BEARING FAILED DURING RETRACTION. THE FAILURE CAUSED THE FLAP TO BIND AND TRIP CIRCUIT BREAKER, BUT NOT UNTIL AFTER THE RT FLAP HAD BEEN DAMAGED BY THE BINDING. THE FLAP SKINS AND SPAR WERE DAMAGED OUTBOARD OF PUSH/PULL ROD. DAMAGED ENOUGH TO WARRANT REPAIR OF FLAP. THE AIRCRAFT WAS INSPECTED PER A 100-HOUR 45 HOURS BEFORE WITH NO DEFECTS FOUND.									
5312	42279 18258940	CESSNA 182L				BULKHEAD 07126161	CRACKED RT RUD STOP	4208	3/5/98 98ZZZX1178
BULKHEAD FOUND CRACKED AT RIGHT RUDDER STOP APPROXIMATELY .50 INCH LONG. REMOVED AND REPLACED BULKHEAD ASSY. THIS REPORT SUBMITTED IN C/W AD 72-07-09.									
3246	4535F 1851021	CESSNA A185E				NUT AN365	STRIPPED LT MLG		3/16/98 98ZZZX1175
DURING SMOOTH LANDING, LEFT WHEEL/TIRE ASSY DEPARTED AIRCRAFT. TIRE/WHEEL ASSY WAS PROPERLY FAA APPROVED, BUT OVERSIZE. NAS BOLTS HOLDING AXLE TO GEAR LEG STRIPPED THROUGH THE AN365 NUTS. RECOMMEND THIS INSTALLATION FOR GRAVEL RUNWAY USE ONLY.									

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
5312	5837F 21058837	CESSNA 210G				BULKHEAD 12128582	CRACKED BS 230.187		3/10/98 98ZZZX1138
	BULKHEAD FOUND CRACKED DURING ANNUAL INSPECTION PER AD 72-07-09. EFFECTIVE DATE 4-1-72.								
5753	94035 21060487	CESSNA T210L				BEARING 0523920	SEIZED FLAP ROLLER	1960	1/26/98 98ZZZX1132
*****	DURING AN ANNUAL INSPECTION TO CHECK FLAP BEARINGS AFTER A FAILURE ON A CE-172, FOUND 10 OUT OF 12 BEARINGS WITH THE NEEDLE BEARINGS SEIZED. NO VISUAL SIGN OF WEAR. CLEANED, LUBED, REINSTALLED. SUBMITTER RECOMMENDED 1,000-HOUR INSPECTIONS REQUIRING REMOVAL.								
5753	94035 21060487	CESSNA T210L				BEARING 0523921	SEIZED FLAP ROLLER	1960	1/26/98 98ZZZX1133
	DURING AN ANNUAL INSPECTION TO CHECK FLAP BEARINGS AFTER A FAILURE ON A CE-172, FOUND 10 OUT OF 12 BEARINGS WITH THE NEEDLE BEARINGS SEIZED. NO VISUAL SIGN OF WEAR. CLEANED, LUBED, REINSTALLED. SUBMITTER RECOMMENDED 1,000-HOUR INSPECTIONS REQUIRING REMOVAL.								
2140	2644U 310R1811	CESSNA 310R			8259JR2	FUEL LINE	CORRODED HEATER		3/4/98 98ZZZX1120
*****	DURING ANNUAL INSPECTION AND BY C/W AD 81-09-09 BY VISUAL INSPECTION, CORROSION WAS FOUND ON THE FORWARD FUEL INLET LINE AFT OF THE HEATER PUMP VALVE. SUBMITTER STATED THIS IS THE THIRD LINE FOUND WITH THIS PROBLEM ON THREE DIFFERENT 310R'S.								
3230	5092P 310P0057	CESSNA 310P				TUBE ASSY 08421211	FAILED NLG	7451	3/9/98 98ZZZX1110
*****	NOSE GEAR ROD END ASSY FAILED. THE BEARING WAS FREE AND NOT SEIZED.								
5312	3038R 320A0038	CESSNA 320A				SUPPORT 081107510	BUCKLED AFT CABIN	13	3/9/98 98ZZZX1112
	DURING ANNUAL INSPECTION, FOUND REAR CABIN BULKHEAD SUPPORT (PN 0811075-10) BUCKLED. UPON FURTHER DISASSEMBLY, FOUND FITTING SEVERELY CORRODED.								
5711	3038R 320A0038	CESSNA 320A				FITTING 08112763	CORRODED SPAR AFT CABIN	13	3/9/98 98ZZZX1113
	DURING ANNUAL INSPECTION, FOUND REAR CABIN BULKHEAD SUPPORT (PN 0811075-10) BUCKLED. UPON FURTHER DISASSEMBLY, FOUND FITTING SEVERELY CORRODED.								
3213 A19R	4104G 340A0279	CESSNA 340A				STRUT 5141001213	WORN LOWER LINK LUG	4400	2/25/98 98ZZZX1161
	INSPECTION OF LOWER GEAR STRUT ASSY FOUND LUG HOLES ELONGATED IN LINE WITH LOWER TORQUE LINK. SUSPECT CORROSION INDUCED WEAK DUE TO POOR LUBE HISTORY AND EXTREME CLIMATE.								
5412 XM8R	340TS 340A0999	CESSNA 340A				HEAT SHIELD 56560061	BURNED LT FIREWALL		2/16/98 98ZZZX1143
	AFTER REMOVAL OF THE LEFT NACELLE COVER AND FUEL CELL, SEVERE CORROSION WAS FOUND. ALSO, AFT SIDE OF LT FIREWALL DISCOLORED FROM HEAT AND THE FUEL CELL HEAT SHIELD IS BURNED THROUGH. THE HEAT DAMAGE IS BELIEVED TO BE CAUSED BY A PREVIOUS EXHAUST FAILURE. THIS AIRCRAFT IS WELL MAINTAINED, HANGARED MOST OF THE YEAR, AND NOT HIGH TIME. SUBMITTER BELIEVES THIS IS A SERIOUS PROBLEM THAT MAY GO UNDETECTED ON MANY SIMILAR AIRCRAFT.								
5700 XM8R	340TS 340A0999	CESSNA 340A				NACELLE 562010022	CORRODED RT WING ASSY	2095	2/16/98 98ZZZX1145
	FUEL LEAKING FROM RT WING FND COMING FROM RT NACELLE FUEL CELL. REMOVED NACELLE ACCESS COVER, FUEL CELL LINER, HEAT SHIELD, AND FUEL CELL. SEVERE CORROSION FND ON UPPER WING SKIN AND STRS. FUEL CELL LINER CORRODED (EXFOLIATED). ALSO, LT NACELLE INSPECTED FOR SIMILAR CONDITION. AFTER REMOVAL OF LT NACELLE COVER AND FUEL CELL, SEVERE CORROSION FND. UPPER WING SKIN, STRINGERS AND UPPER SPAR CAP ARE ALL EXFOLIATED. AFT SIDE OF LT FIREWALL DISCOLORED FROM HEAT AND FUEL CELL HEAT SHIELD IS BURNED THROUGH. HEAT DAMAGE MAY BE CAUSED BY A PREVIOUS EXH FAILURE. ACFT IS WELL MAINTAINED, HANGARED MOST OF THE YEAR AND NOT HIGH TIME. SUBMITTER BELIEVES THIS IS A PROBLEM THAT MAY GO UNDETECTED ON SIMILAR ACFT.								

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
5700 XM8R	340TS 340A0999	CESSNA 340A				NACELLE 562010023	CORRODED LT WING ASSY	2095	2/16/98 98ZZZX1144
*****	FUEL LEAKING FROM RT WING FND COMING FROM RT NACELLE FUEL CELL. REMOVED NACELLE ACCESS COVER, FUEL CELL LINER, HEAT SHIELD, AND FUEL CELL. SEVERE CORROSION FND ON UPPER WING SKIN AND STRS. FUEL CELL LINER CORRODED (EXFOLIATED). ALSO, LT NACELLE INSPECTED FOR SIMILAR CONDITION. AFTER REMOVAL OF LT NACELLE COVER AND FUEL CELL, SEVERE CORROSION FND. UPPER WING SKIN, STRINGERS AND UPPER SPAR CAP ARE ALL EXFOLIATED. AFT SIDE OF LT FIREWALL DISCOLORED FROM HEAT AND FUEL CELL HEAT SHIELD IS BURNED THROUGH. HEAT DAMAGE MAY BE CAUSED BY A PREVIOUS EXH FAILURE. ACFT IS WELL MAINTAINED, HANGARED MOST OF THE YEAR AND NOT HIGH TIME. SUBMITTER BELIEVES THIS IS A PROBLEM THAT MAY GO UNDETECTED ON SIMILAR ACFT.								
2510	87144 402B0933	CESSNA 402B				BRACKET	FAILED PILOT SEAT BACK		2/25/98 98ZZZX1174
*****	PILOT SEAT BACK RECLINED IN-FLIGHT. BRACKET ON RIGHT SIDE OF SEAT BROKEN. CASTING APPEARS TO HAVE BEEN CRACKED PRIOR TO FAILURE.								
2731	PHECA 0321	CESSNA 414A				ELEV TAB	MISRIGGED ELEV TRIM	3700	3/8/98 98ZZZX1181
*****	DURING A 1,000 HR INSP ON RUD-AIL, AND ELEV TRIM IAW CE 414 SM, REV 31, FOUND ELEV TRIM TAB TRAVEL WAS 12 DEG UP/21 DEG DOWN. CHECKED MANUAL FOR TRAVELS OF TRIM TABS AND FOUND IN MM, REV 31, RIGGINGS FOR ELEV TRIM TAB UP: 5 DEG AND DOWN: 30 DEG. DOUBLE CK MM REV HISTORY, FOUND ELEV TRIM TAB TRAVELS ALTERED WITH MM REV 31, DATED 2-3-97. (OLD TRAVELS WERE: 12 DEG UP AND 20 DEG DOWN, TOL. +1 DEG). DURING INSTALL, SET TRAVELS IAW MM REV 31: 5 DEG UP AND 30 DEG DOWN. FIRST FLIGHT (TRIM NEUTRAL) ACFT EXPERIENCED A NOSE UP AT TAKE OFF THAT COULD NOT BE CORRECTED BY TRIMMING THE ELEV; IT WAS AGAINST ITS 'NOSE DOWN' STOP, AND FORCE HAD TO BE IMPOSED UPON COLUMN TO KEEP ACFT IN LEVEL FLIGHT.								
5610	88584 421C0642	CESSNA 421C				WINDSHIELD 5111604202	DEPARTED COPILOT	7500	12/1/97 98ZZZX1173
	AS THE AIRCRAFT LEVELLED OFF AT 23,000 FEET MSL, THE COPILOT'S WINDSHIELD DEPARTED THE AIRCRAFT WITH ONLY APPROXIMATELY 10 PERCENT REMAINING ATTACHED TO THE AIRFRAME. SPECULATING THAT THE CRACK ORIGINATED AT THE RIGHT LOWER CORNER AND WENT STRAIGHT UP TO THE TOP OF THE WINDSHIELD. SUBMITTER STATED TO PREVENT, SHOULD HAVE RECURRING INSPECTION. REF: MEB 83-33R.								
7120 WTXR	441W 4410181	CESSNA 441				MOUNT 57510061	CRACKED LT ENG INBD	5039	2/12/98 98ZZZX1122
*****	WHILE INVESTIGATING A ROUGH ENGINE, FOUND AN ENGINE MOUNT TUBE CRACKED THROUGH ON LT ENGINE INBOARD, UPPER CLUSTER, LOWER TUBE. INSTALLED DIFFERENT REPAIRED TRUSS.								
2430	19PV 560416	GULSTM 560				GROUND CONNECT	LOOSE START/GENERATOR	514	3/13/98 98ZZZX1169
*****	PILOTS REPORTED A PARALLELING PROBLEM WITH THE GENERATORS. INSPECTION REVEALED BOTH STARTER/GENERATOR GROUND CONNECTIONS WERE LOOSE. MINOR ARCING WAS NOTED ON LEFT GROUND. BOTH CONNECTIONS WERE CLEANED AND RESEATED. THIS CONDITION RESULTED FROM IMPROPER TORQUE OF ATTACHING HARDWARE.								
2434	727MB 61P079680634	PIPER PA60601P			ELECTROSYS	ALTERNATOR 02035	FAILED		3/16/98 98ZZZX1114
	OVERHAULED ALTERNATOR FROM ELECTROSYSTEMS FAILED 3 HOURS INTO FIRST FLIGHT AFTER INSTALLING. (INTERNAL FAILURE).								
2750		PIPER PA28140				SPRING 6282000	FAILED FLAP RETURN	4400	3/10/98 98ZZZX1124
	DURING PRE-FLIGHT INSPECTION, PILOT PUSHED DOWNWARD ON FULLY EXTENDED FLAPS, HEARD SNAPPING NOISE AND NOTICED FLAPS EXTENDED AN ADDITIONAL 5 DEGREES BEYOND FULL EXTENDED POSITION AND LOCKED. FLAPS COULD NOT BE RAISED WITH FLAP CONTROL HANDLE. MAINTENANCE INVESTIGATION REVEALED THAT FLAP RETURN SPRING HAD BROKEN WHERE IT ATTACHES TO FLAP TORQUE TUBE SPROCKET CHAIN ALLOWING CHAIN TO DROP ONTO SPROCKET AND JAM BETWEEN LOWER FLAP INPUT CHAIN AND SPROCKET. SYSTEM IS DESIGNED SO THAT SPROCKET TOOTH AND SPRING ATTACH END ARE FORCED TO SHARE THE SAME CHAIN LINK WHENEVER FLAP CONTROL HANDLE IS PULLED FULL AFT. THIS NICKS SPRING AT ATTACH POINT AND EVENTUALLY CAUSES BREAKAGE.								

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2810	8777W 2810321	PIPER PA28235				FUEL TANK	MISINSTALLED LT/RT MAIN	2/1/98 98ZZZX1118	
FOUND LT AND RT MAIN FUEL TANKS INSTALLED WITH AN 526-C NON-STRUCTURAL SCREWS OF ASSORTED WRONG LENGTHS. THIS INSTALLATION CALLS FOR 60 EACH MS 27039C-8-12 (OR EQUIVALENT) STRUCTURAL SCREWS ALONG THE SPAR, TOP AND BOTTOM, AND 80 EACH MS 27039C-8-9 SCREWS ALONG THE SIDES OF THE TANKS. THESE TANKS WERE REPAIRED AND INSTALLED IN JANUARY, 1997 (BY OWNER RECOLLECTION). AIRCRAFT RECORDS NOT AVAILABLE FOR EXACT DATES AND TIMES.									
3246 MOGR	2558M 287890256	PIPER PA28181			PARKERHANFIN	WHEEL 04008602	CRACKED BOLT HOLE	3592 98ZZZX1107	2/23/98
WHILE CHANGING TIRE, FOUND WHEEL CRACKED AT BOLT HOLE. HOLE APPEARED TO BE DRILLED OFF-CENTER. ALSO, AREA BELOW TIRE BEAD GOUGED PREVIOUSLY BY SHARP OBJECT USED TO BREAK TIRE LOOSE. WHEEL REPLACED WITH NEW.									
3246 MOGR	2558M 287890256	PIPER PA28181				WHEEL 04008602	GOUGED BEAD AREA	3592 98ZZZX1106	2/23/98
WHILE CHANGING TIRE, FOUND AREAS BELOW TIRE BEAD AREAS SEVERELY GOUGED BY SHARP TOOL. WHEEL WAS REPLACED WITH NEW.									
5711 *****	600AA 2825102	PIPER PA28140				SPAR CAP	CORRODED AFT SPAR CAP	4577 98ZZZX1172	3/18/98
DURING WING INSPECTION, FOUND EVERY WHERE THAT SOUNDPROOF INSULATION COMES IN CONTACT WITH THE FERROUS AFT SPAR CAP, THAT CORROSION SETS IN DUE TO THE MOISTURE THAT THE INSULATION HOLDS.									
7820 MOGR	2558M 287890256	PIPER PA28181				MUFFLER 6751700	FAILED ENGINE	3592 98ZZZX1105	2/23/98
DURING ANNUAL INSPECTION, ENGINE FOUND RUNNING RICH AND WOULD NOT DEVELOP FULL POWER. TROUBLESHOOTING REVEALED MUFFLER TAILPIPE 50 PERCENT BLOCKED BY FAILED BLAST TUBE. MUFFLER WAS REMOVED,									
2140 *****	63ND 317852098	PIPER PA31350				HEATER B405065D722	FAILED FORWARD	362 98ZZZX1123	3/5/98
DURING FLIGHT, THE COCKPIT FILLED WITH A GREENISH, YELLOW SMOKE EMANATING FROM THE DEFROST AND HEATER DUCTS. PILOT SHUT DOWN THE FORWARD HEATER AND EVACUATED THE SMOKE FROM THE CABIN. THE FLIGHT CONTINUED TO THE ORIGINAL DESTINATION. THE AIRCRAFT WAS INSPECTED AND FOUND UNDamaged. THE FORWARD HEATER HAD OVERHEATED. WITHOUT FURTHER INSPECTION OF THE HEATERS, THE DAMAGE AND SYMPTOMS ARE CONSISTENT WITH A PERFORATED BURNER CAN. THIS COMBUSTION HEATER HAD A PRESSURE DECAY TEST IAW AD 96-20-07 ON 1-18-98, AND HAD ACCUMULATED 62.4 HEATER HOURS OF OPERATION SINCE THAT DATE.									
6120	112AG 31698	PIPER PA31310				BRACKET 4090500	FAILED PROPELLER CABLE	11740 98ZZZX1177	2/12/98
UPON TRYING TO REDUCE TO CLIMB POWER, THE RIGHT PROP CONTROL WAS STIFF WHEN MORE PRESSURE APPLIED. THE CONTROL BROKE FREE, BUT THE RPM DID NOT CHANGE. FOUND PROP CABLE HOLD-DOWN BRACKET BROKEN AND CABLE STIFF. FREED UP CABLE AND REPLACED BRACKET. OPERATIONAL CHECK OK. SUGGEST STIFF CABLES BE REPORTED AND CORRECTED TO PRECLUDE BREAKING OF KEEPER WITH LOSS OF CONTROL EFFECTIVITY.									
2434 ONFR	22382 347870459	PIPER PA34200T			PRESTOLITE	ALTERNATOR ALX9425B	FAILED BRUSH HOLDER	2/24/98 98ZZZX1126	
ALTERNATOR FAILED AFTER 2 MINUTES OF OPERATION. FOUND OPEN FIELD CIRCUIT. FOUND RED SILICONE SEALANT TYPE MATERIAL AROUND BRUSH HOLDER PREVENTING BRUSH SEATING ON SLIP RING. CAME FROM OVERHAUL THIS WAY.									

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT)

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS**3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2312 HEEA	10761 45381	BELL 206L1			RT13	TRANSCEIVER 4000102000	FAILED COCKPIT		3/18/98 HEEA0013374
NO 5 VOLTS OUT OF POWER SUPPLY AND CHECK TONES FOR PROPER OPERATION.									
2562 HEEA	513EH 45421	BELL 206L1			NARCO	ELT ELT910	DEFECTIVE COCKPIT		3/4/98 HEEA0013272
NARCO ELT BATTERY WEAK.									
2810 HEEA	22751 3627	BELL 206B3				FUEL CELL 206061661103	CRACKED FUEL SYS		3/18/98 HEEA0013404
EXCESSIVE CRACKS ON SEAMS AND SEEPAGE THROUGH FABRIC.									
3213	701MP 7221270	BELL OH58A			058321300	SADDLE 601051001	FAILED HI SKID GEAR	5	2/20/98 98ZZZX1146
WHILE GROUND HANDLING HELICOPTER, SKID EAR BROKE OFF. EAR MIGHT BE HARDENED TOO MUCH CAUSING IT TO BE BRITTLE.									
3416 HEEA	3207Q 51540	BELL 206L3				ALT ENCODER A30	FAILED COCKPIT		3/18/98 HEEA0013386
ENCODER HAS NO VALID OUTPUT.									
3421 HEEA	42EA 51542	BELL 206L3				ATTITUDE GYRO 206075607103	FAILED COCKPIT		3/18/98 HEEA0013395
ATTITUDE GYRO PRECESSES AND WILL NOT CAGE.									
3424 HEEA	2251Z 45756	BELL 206L1				INDICATOR A593002	FAILED COCKPIT T&B		3/18/98 HEEA0013396
T&B INDICATOR IS NOT WORKING.									
3424 HEEA	6251V 51404	BELL 206L3				INDICATOR 206070274005	FAILED COCKPIT T&B		3/18/98 HEEA0013397
INDICATOR "DEAD" IS INOPERATIVE AND NEEDS LIGHT.									
3453 HEEA	513EH 45421	BELL 206L1			KA83	ANTENNA 071143100	FAILED LORAN		3/18/98 HEEA0013372
LORAN HAS NO SIGNAL WITH THIS ANTENNA. BAD FROM STOCK.									
6710 HEEA	31801 51074	BELL 206L3				ACTUATOR 206062721109	FAILED M/R		3/18/98 HEEA0013407
BEEP RANGE WILL NOT STAY AT MAX. OR MIN. POSITION.									
3442 HEEA	102PH 30899	BELL 212			P40001	INDICATOR MI5852013	FAILED COCKPIT		3/18/98 HEEA0013361
THE CONTRAST IS NOT BRIGHT ENOUGH TO READ THE SCREEN. THERE IS ONLY ONE COLOR. VERIFIED, FOUND INTENSITY KNOB TURNED DOWN, ALSO FOUND YELLOW DISPLAY PROBLEM ON MEMORY BOARD. REPLACED IC15, U1011, U1017, U1015, U1014, U1008, U1009. REPAIRED. BENCH CHECK GOOD.									
2432 HEEA	8045T 28101	BELL 214ST				CHARGER 214175379103	FAILED BATTERY		3/18/98 HEEA0013401
CHARGER INOPERATIVE. BATTERY NEVER SHOWS TOP CHARGE.									

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2432 HEEA	6957Y 28139	BELL 214ST				CHARGER 214175379103	FAILED BATTERY		3/18/98 HEEA0013400
CHARGER WON'T CHARGE BATTERY.									
2436 HEEA	3897N 28106	BELL 214ST				REGULATOR 214175153105	FAILED GEN VOLTAGE		3/18/98 HEEA0013389
NO GENERATOR OUTPUT. VOLTAGE REG FAILED.									
2810 HEEA	59806 28140	BELL 214ST				FUEL CELL 214066255103	LEAKING SEAMS		3/18/98 HEEA0013379
FUEL CELL LEAKING. DETERIORATED SEAMS.									
2932 HEEA	6957Y 28139	BELL 214ST				PRESSURE SWITCH 205076044009	FAILED HYD SYS		3/18/98 HEEA0013402
PRESSURE SWITCH FAILED									
6330 HEEA	3897N 28106	BELL 214ST				BEARING 214031615105	SEPARATED CLEVIS ARM ASSY		3/18/98 HEEA0013380
ELASTOMER BEARING SEPARATED.									
7714 HEEA	59806 28140	BELL 214ST				PANEL ASY 214175428101	FAILED ENGINE GAUGE		3/18/98 HEEA0013409
ENGINE RPM WORKS INTERMITTENTLY.									
6300 HEEA	230UN 23009	BELL 230			230030535101	BEARING 230330509101	WORN M/R DRIVE		3/18/98 HEEA0013368
BEARINGS WORN. REPLACED WITH SERVICEABLE PART.									
6300 HEEA	230UN 23009	BELL 230			222331618105	BEARING 222330619101	WORN M/R DRIVE		3/18/98 HEEA0013369
BEARINGS WORN. REPLACED WITH SERVICEABLE PART.									
6300 HEEA	230UN 23009	BELL 230			222010509105	BUSHING 20012403528	DAMAGED M/R DRIVE		3/18/98 HEEA0013370
BUSHING DAMAGED. REPLACED WITH SERVICEABLE PART.									
6400 HEEA	230UN 23009	BELL 230				BEARING 222312712001	DAMAGED T/R		3/18/98 HEEA0013363
BEARING WORN AND DAMAGED. REPLACED WITH SERVICEABLE PART.									
6400 HEEA	230UN 23009	BELL 230			222012711107	BEARING 222312751001	WORN T/R CNTR WT		3/18/98 HEEA0013364
BEARINGS WORN. REPLACED WITH SERVICEABLE PART.									
6700 HEEA	230UN 23009	BELL 230			222001383101	BEARING MS276475	ROUGH FLT CONTROL		3/18/98 HEEA0013371
BEARING ROUGH. REPLACED WITH SERVICEABLE PART.									

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
6710 HEEA	230UN 23009	BELL 230			222382001105	BEARING 212010782101	WORN M/R CONTROL		3/18/98 HEEA0013367
BEARINGS WORN. REPLACED WITH SERVICEABLE PART.									
6710 HEEA	230UN 23009	BELL 230			222382001105	BEARING 212010782101	WORN M/R CONTROL		3/18/98 HEEA0013365
BEARINGS WORN. REPLACED WITH SERVICEABLE PART.									
6710 HEEA	230UN 23009	BELL 230			222382001105	BEARING 212010782101	WORN M/R CONTROL		3/18/98 HEEA0013366
BEARINGS WORN. REPLACED WITH SERVICEABLE PART.									
2435 HEEA	403PH 53177	BELL 407				STARTER 206062200113	FAILED ENG START/GEN	527	3/17/98 HEEA0013350
STARTER TURNED SLOWLY AND CHATTERED. INSPECTED BY ACCESSORY OVERHAUL SHOP AND FOUND ALL FOUR BOTTOM BRUSHES BROKEN AND LEADS SEPARATED FROM BRUSHES AND COMMUTATOR WAS EXCESSIVELY PITTED. OVERHAULED STARTER GENERATOR AND RETURNED TO SERVICE.									
3310 HEEA	510PH 53209	BELL 407				LIGHT ASSY 900044	FAILED COCKPIT		3/17/98 HEEA0013356
LIGHT STAYS ON.									
6320 HEEA	467PH 53142	BELL 407				INDICATOR 407375005101	FAILED XMSN OIL	177	3/18/98 HEEA0013410
NO PRESSURE INDICATION POWER. XMSN OIL TEMP/PRESS									
6320 HEEA	510PH 53209	BELL 407				PRESSURE SWITCH 214040806003	FAILED TRANSMISSION	77	3/17/98 HEEA0013358
TRANS. PRESS CAUTION LIGHT WILL NOT ILLUMINATE.									
2120 HEEA	3893P 33012	BELL 412				SERVO 212073927003	FAILED AIR DIST		3/18/98 HEEA0013375
SERVO CONTROLLER MOTORS RUNS CONSTANTLY.									
2841 HEEA	2298Z 33077	BELL 412				INDICATOR 393008047	FAILED FUEL QTY		3/18/98 HEEA0013362
GAUGE DROPS TO ZERO OR DOWN 1000 POUNDS FROM TIME TO TIME. REPLACED WITH SERVICEABLE PART.									
2841 HEEA	23023 33080	BELL 412				SWITCH 384178103	FAILED FUEL SYS		3/18/98 HEEA0013383
CAPACITANCE OUT OF TOLERANCE.									
2842 HEEA	3893P 33012	BELL 412				PROBE 391046199	FAILED FUEL QTY		3/18/98 HEEA0013381
PROBE WILL NOT TEST.									
2842 HEEA	2261D 33076	BELL 412				TRANSMITTER 2003600000102	FAILED FUEL QTY		3/18/98 HEEA0013387
WILL NOT TRANSMIT SIGNAL									

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2842 HEEA	23023 33080	BELL 412				PROBE 391046200	FAILED FUEL QTY		3/18/98 HEEA0013382
PROBE CAUSES INDICATOR TO RISE 200 LBS.									
3424 HEEA	3893L 33006	BELL 412				RATE GYRO 214075244001	ERRATIC COCKPIT		3/18/98 HEEA0013392
RATE GYRO ERRATIC INDICATION.									
3424 HEEA	6559Z 36019	BELL 412				RATE GYRO 214075244001	FAILED COCKPIT		3/18/98 HEEA0013393
RATE GYRO INOPERATIVE.									
3452 HEEA	6559Z 36019	BELL 412				CONTROL 071119218	FAILED COCKPIT		3/18/98 HEEA0013373
TRANSPONDER DOES NOT TEST PROPERLY AND NO LIGHTS TO SHOW MODE IT IS IN.									
6710 HEEA	5759N 33002	BELL 412				ACTUATOR ROTARY 214001347005	BINDING M/R		3/18/98 HEEA0013398
ROTARY ACTUATOR BINDING.									
6710 HEEA	3893P 33012	BELL 412				ACTUATOR ROTARY 214001347005	FAILED M/R		3/18/98 HEEA0013388
MAG BRAKE INTERMITTENT -- AUTO TRIM NOT WORKING.									
6710 HEEA	7128R 36007	BELL 412				ACTUATOR ROTARY 214001347005	FAILED CYCLIC		3/18/98 HEEA0013376
SYSTEM CYLIC WOULD NOT MOVE WHEN BEEPED.									
7210 HEEA	2014K 33020	BELL 412	PWA PT6T3B			COMBINING GRBOX 3024780	MAKING METAL ENGINE	4357	3/18/98 HEEA0013377
COMBINING GEAR BOX MAKING METAL.									
7714 HEEA	2261D 33076	BELL 412				INDICATOR 212075037101	STICKING ENGINE N1		3/18/98 HEEA0013403
INDICATOR IS STICKING.									
7722 HEEA	2261D 33076	BELL 412				INDICATOR 212075067109	FAILED ENG ITT		3/18/98 HEEA0013391
WILL NOT INDICATE.									
7722 HEEA	2261D 33076	BELL 412				INDICATOR 212075067105	FAILED ENG ITT		3/18/98 HEEA0013390
WILL NOT INDICATE.									
7722 HEEA	23023 33080	BELL 412				TRIM COMPENSATOR 3030083	FAILED ENG TRIM		3/18/98 HEEA0013394
READS 80 DEGREES TOO HIGH. ENGINE TRIM COMPENSATOR FAILED.									

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2612 CHIR	CFHFW 107	BOEING 1072			KIDDE	FIRE DETECTOR 61423473275	MALFUNCTIONED NR 2 AFT UPPER	679	3/22/98 CHI2069
DETECTOR FAILED, CAUSED NR 2 FIRE LIGHT TO FALSELY ILLUMINATE. DETECTOR SENT TO MFG FOR EVALUATION. THIS DETECTOR IS PART OF STC SR00375SE. (X)									
3416 HEEA	967MB S737	BOLKMS BO105S				ALT ENCODER A30	FAILED COCKPIT		3/18/98 HEEA0013385
ALT ENCODER HAS NO VALID OUTPUT.									
7714 HEEA	5421E S806	BOLKMS BO105S				TACH-GENERATOR 32005008	MALFUNCTION ENGINE		3/17/98 HEEA0013351
FROM STOCK, INSTALLED IN AIRCRAFT DURING GROUND RUN, HAD NO NEEDLE INDICATION ON TRIPLE TACH INDICATOR. INSPECTED AND TESTED BY ACCESSORY OVERHAUL SHOP AND COULD NOT FIND ANY PROBLEM WITH TACH GENERATOR, IT TESTED OK AND WAS RETURNED TO SERVICE.									
7931 HEEA	911EB S812	BOLKMS BO105S				INDICATOR 4011001	FAILED NR 2 ENG OIL		3/18/98 HEEA0013384
NR2 ENGINE OIL PRESSURE HIGH AT 100%.									
7230 R7MA	158BK 7058	BOLKMS BK117A3	LYC LTS101650B1			SEAL 430404701	LEAKING LT ENGINE NR 1		7/28/97 98ZZZX1149
LEFT ENGINE NR 1 BEARING LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	127HH 7060	BOLKMS BK117A3	LYC LTS101650B1			SEAL 430150601	LEAKING RT ENG NR 2	709	12/9/97 98ZZZX1148
RIGHT ENGINE NR 2 BEARING LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	424MB 7082	BOLKMS BK117A3	LYC LTS101650B1			SEAL 430150601	LEAKED LT ENG NR 2		7/24/97 98ZZZX1151
LEFT ENGINE NR 2 BEARING SEAL, UPON INSTALLATION, UNIT LEAKED BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	911BY 7127	BOLKMS BK117A4	LYC LTS101650B1			BEARING 430124203	PITTED ENGINE COMPR	860	1/9/96 98ZZZX1160
COMPRESSOR BEARING HAS EXCESSIVE PITTING. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	911BY 7127	BOLKMS BK117A4	LYC LTS101650B1			SEAL 430150601	LEAKING RT ENG NR 2	763	1/9/96 98ZZZX1158
RIGHT ENGINE NR 2 BEARING SEAL LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM. ACTUAL P/N INSTALLED, 4-141-45-02, SN 390.									
7230 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			SEAL 430150601	LEAKING LT ENG NR 2	378	11/18/97 98ZZZX1156
LEFT ENGINE NR 2 BEARING LEAKING BEYOND SERVICEABLE LIMITS. ACTUAL PART NUMBER INSTALLED, 4-301-357-03. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			BEARING 430151801	WORN LT ENGINE NR 2	378	11/18/97 98ZZZX1155
LEFT ENGINE NR 2 BEARING HAS EXCESSIVE ROLLER WEAR. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7250 R7MA	158BK 7058	BOLKMS BK117A3	LYC LTS101650B1			SEAL 430144801	LEAKING LT ENG NR 3	260	7/28/97 98ZZZX1150
LEFT ENGINE NR 3 BEARING LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
7250 R7MA	911BY 7127	BOLKMS BK117A4	LYC LTS101650B1			SEAL 430144801	LEAKING RT ENGINE NR 3	763	1/9/96 98ZZZX1159
RIGHT ENGINE NR 5 BEARING SEAL LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7250 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			BEARING 414144001	PITTED ENGINE NR 1	378	11/18/97 98ZZZX1157
LEFT ENGINE BEARING HAS EXCESSIVE PITTING. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7250 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			ROTOR ASSY 414129001	SHIFT PT BLADE	756	8/22/97 98ZZZX1153
ENGINE FAILED SB LT101-72-10-0153. EXCESSIVE IBPT BLADE SHIFT Q-ROTOR = 6.77 GMIN2. REPLACED WITH NEW UNIT, CORRECTED PROBLEM. PART TC: 3,128.1.									
7250 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			BEARING 430102301	PITTED RT ENGINE	756	8/22/97 98ZZZX1152
RIGHT ENGINE BEARING HAS EXCESSIVE PITTING. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7712 R7MA	586BH 7129	BOLKMS BK117A4				SHAFT 408104917	GROOVED TORQUEMETER	756	8/22/97 98ZZZX1154
TORQUE METER SHAFT UNIT EXCESSIVELY GROOVED. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
6310 FSPA	5695B 1204	ENSTRM 280C				STRUT BEARING ECD01413	CRACKED M/R DRIVE	18	2/19/98 98ZZZX1111
CAGE OF UPPER JACK STRUT BEARING WAS FOUND BROKEN DURING ANNUAL INSPECTION WHILE GREASING BEARING. THIS WAS THE SECOND BEARING FOUND IN THIS CONDITION. IT SHOULD BE NOTED THIS BEARING HAS A 600-HOUR LIFE LIMIT AND A 100-HOUR LUBE SCHEDULE. SUBMITTER STATED THIS BEARING WAS ORIGINALLY INTENDED TO BE HAND-PACKED.									
7322	550JM 0013E	HUGHES 369E	ALLSN 250C20B		BENDIX 23057344	FUEL CONTROL 252464429	MALFUNCTIONED ENGINE	2/23/98	98ZZZX1147
ENGINE STILL HAVING DELAYED STARTS. ENGINE FLAMED OUT AT IDLE. RESTARTED WITH THE START PUMP ON, AND FLAMED OUT DURING THE START SEQUENCE. RESTARTED AGAIN, MADE IT TO IDLE, BUT FLAMED OUT AGAIN. REMOVED THE FUEL CONTROL AND INSTALLED A DASH 28 UNIT. NO FURTHER PROBLEMS. TIME ON FUEL CONTROL SN 310785 WAS 1237.5 HOURS TSO, AND 31.6 HOURS SINCE REPAIR.									
7323 JP0M	50AP 1090585D	HUGHES 369D	ALLSN 250C20B		BENDIX 23057870	FLYWEIGHT BUSH 2539034	WORN N2 GOVERNOR	2/10/98 1052	98ZZZX1026
PILOT EXPERIENCED DROOP OF N2 RPM (ROTOR) TO 100 PERCENT. BEEFED UP TO 102 PERCENT, THEN N2 RPM WENT UP TO 104 PERCENT. ERRATIC OPERATION NOTICED. RETURNED GOVERNOR TO REPAIR STATION FOR REPAIR AND REINSTALLED. PROBLEM CORRECTED.									
6710	159RP 0342	ROBSIN R44			C5811	SPRING ASSY C0561	FAILED LATERAL TRIM	199	3/12/98 98ZZZX1164
*****	WHILE PERFORMING INSPECTION FOR AD 98-06-12, FOUND LATERAL TRIM SPRING ASSY PULLED COMPLETELY OUT OF MOUNTING BLOCK AND DANGLING AGAINST BELLY SKIN. TRIM MOTOR ARM P/N C581-1 FROZEN ON SPRING SHAFT. SUBMITTER STATED HAD THIS UNIT FAILED IN-FLIGHT, LOSS OF CONTROL WOULD HAVE BEEN POSSIBLE. THE REPLACEMENT SPRING ASSY LOWER BEARING IS STAKED INTO THE MOUNTING BLOCK, YET THIS IS NOT THE CAUSE OF THE AD. SUBMITTER RECOMMENDED REVISION OF AD 98-04-12 TO REQUIRE IMMEDIATE REPLACEMENT OF AFFECTED SPRING ASSY REGARDLESS OF SHAFT WEAR.								
6710	972SA 0394	ROBSIN R44				SHAFT C5851	WORN CYCLIC CONTROL	63	1/22/98 98ZZZX1115
*****	ROTORCRAFT EXPERIENCED A PARTIAL CYCLIC CONTROL FAILURE WHILE LANDING. PILOT WAS UNABLE TO ROLL LEFT USING CYCLIC INPUT. INVESTIGATION REVEALED THAT LATERAL TRIM ACTUATOR ASSEMBLY SHAFT, PN C585-1, HAD A STEP WORN IN IT WHICH ALLOWED THE TRIM ACTUATOR TO JAM. THREE ADDITIONAL AIRCRAFT INSPECTED REVEALED THE SAME PROBLEM. LATERAL TRIM ACTUATOR ASSEMBLY WAS REPLACED ON ALL 4 AIRCRAFT. SAFETY RECOMMENDATIONS SUBMITTED. AD 98-04-12 ISSUED TO INSPECT AND CORRECT THIS PROBLEM ON ALL R44 HELICOPTERS.								

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2913 HEEA	476X 760436	SKRSKY S76C			ABEX	PUMP 7665009808102	FAILED NR 1 HYD	2387	3/5/98 98ZZZX1163
LOST NR 1 HYDRAULIC SYSTEM PRESSURE IN-FLIGHT. LANDED ON OFFSHORE PLATFORM WITHOUT INCIDENT. MAINTENANCE FOUND HYDRAULIC PUMP FAILURE (INTERNAL METAL CONTAMINATION). REF: S-76 IPC, CHAPTER 29-20-01, FIG 1, ITEM 11.									
7810 HEEA	5128 760181	SKRSKY S76A				EJECTOR 7630507003044	CRACKED EXHAUST		3/18/98 HEEA0013378
EXH EJECTOR CRACKED.									
3120	4055L 2916	SNIAS AS350B2				RELAY V23154C0721GB104	FAILED HOBBS METER	2/15/98	98ZZZX1116
DISCREPANCY IN THE HOUR METER. TIME WAS LESS THAN ACTUAL FLIGHT TIME. T/S OF THE METER REVEALED THERE WAS NO POWER AVAILABLE TO HOBBS METER. DISCOVERED THE RELAY WAS HALF FILLED WITH WATER AND THE PINS IN THE SOCKET HAD RUSTED OFF. UPON EVALUATING THE FAILURE NOTED THE RELAYS ARE NOT SEALED, AND EACH RELAY IS INSERTED IN A SOCKET WHICH CONTRIBUTES TO POOR CONTACT AND THE POTENTIAL FOR CORROSION. THE LOCATION OF THE RELAYS IS SUCH THAT THE AIR CONDITIONING CONDENSATION WILL AMOST CERTAINLY DRIP ON THE RELAYS. SOLUTION WOULD BE TO INSTALL HERMETICALLY SEALED RELAYS J2K-4730-107P OR EQUIVALENT AND MOUNT THEM TO THE PANEL NEXT TO THE HOUR METER.									
3340 HEEA	60951 2771	SNIAS AS350B				POWER SUPPLY 356H2802	FAILED STROBE	247	3/17/98 HEEA0013354
STROBE POWER SUPPLY INOPERATIVE.									
3340 HEEA	6097Z 2820	SNIAS AS350B2				POWER SUPPLY A490ATSDF1428	FAILED STROBE		3/17/98 HEEA0013353
WILL NOT FIRE ANTI-COLLISION LIGHT.									
6210 HEEA	6097Z 2820	SNIAS AS350B2				BLADE 355A11002012	CRACKED M/R	3611	3/17/98 HEEA0013357
M/R BLADE CRACKED.									
6330 HEEA	60951 2771	SNIAS AS350B				BEARING 704A33633151	DAMAGED TRANSMISSION		3/17/98 HEEA0013352
TRANSMISSION BEARING OIL SOAKED.									
6330 HEEA	6097Z 2820	SNIAS AS350B2				SPHERICAL STOP 704A3363310951	WORN TRANSMISSION	1814	3/17/98 HEEA0013355
SPHERICAL STOP ASSY WORN. SERIAL NUMBERS REMOVED ARE 10952, 10948, AND 10956.									
6410 HEEA	60951 2771	SNIAS AS350B			355A12004005	BEARING 704A33633091	SEPARATED T/R BLADE	1233	3/17/98 HEEA0013359
LAMINATED BEARINGS SEPARATED.									
6410 HEEA	4031L 2907	SNIAS AS350B2				BLADES 355A12004008	DAMAGED T/R	509	3/18/98 HEEA0013406
DAMAGE ON T/R BLADES LEADING EDGE NEAR ROOT IN AREA (F).									

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS)

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES**3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
7210 HEEA	2014K 33020	BELL 412	PWA PT6T3B			COMBINING GRBOX 3024780	MAKING METAL ENGINE	4357	3/18/98 HEEA0013377
COMBINING GEAR BOX MAKING METAL.									
7230 R7MA	158BK 7058	BOLKMS BK117A3	LYC LTS101650B1			SEAL 430404701	LEAKING LT ENGINE NR 1		7/28/97 98ZZZX1149
LEFT ENGINE NR 1 BEARING LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	127HH 7060	BOLKMS BK117A3	LYC LTS101650B1			SEAL 430150601	LEAKING RT ENG NR 2	709	12/9/97 98ZZZX1148
RIGHT ENGINE NR 2 BEARING LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	424MB 7082	BOLKMS BK117A3	LYC LTS101650B1			SEAL 430150601	LEAKED LT ENG NR 2		7/24/97 98ZZZX1151
LEFT ENGINE NR 2 BEARING SEAL, UPON INSTALLATION, UNIT LEAKED BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	911BY 7127	BOLKMS BK117A4	LYC LTS101650B1			BEARING 430124203	PITTED ENGINE COMPR	860	1/9/96 98ZZZX1160
COMPRESSOR BEARING HAS EXCESSIVE PITTING. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	911BY 7127	BOLKMS BK117A4	LYC LTS101650B1			SEAL 430150601	LEAKING RT ENG NR 2	763	1/9/96 98ZZZX1158
RIGHT ENGINE NR 2 BEARING SEAL LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM. ACTUAL P/N INSTALLED, 4-141-45-02, SN 390.									
7230 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			SEAL 430150601	LEAKING LT ENG NR 2	378	11/18/97 98ZZZX1156
LEFT ENGINE NR 2 BEARING LEAKING BEYOND SERVICEABLE LIMITS. ACTUAL PART NUMBER INSTALLED, 4-301-357-03. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7230 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			BEARING 430151801	WORN LT ENGINE NR 2	378	11/18/97 98ZZZX1155
LEFT ENGINE NR 2 BEARING HAS EXCESSIVE ROLLER WEAR. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7250 R7MA	158BK 7058	BOLKMS BK117A3	LYC LTS101650B1			SEAL 430144801	LEAKING LT ENG NR 3	260	7/28/97 98ZZZX1150
LEFT ENGINE NR 3 BEARING LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7250 R7MA	911BY 7127	BOLKMS BK117A4	LYC LTS101650B1			SEAL 430144801	LEAKING RT ENGINE NR 3	763	1/9/96 98ZZZX1159
RIGHT ENGINE NR 5 BEARING SEAL LEAKING BEYOND SERVICEABLE LIMITS. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7250 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			BEARING 414144001	PITTED ENGINE NR 1	378	11/18/97 98ZZZX1157
LEFT ENGINE BEARING HAS EXCESSIVE PITTING. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7250 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			ROTOR ASSY 414129001	SHIFT PT BLADE	756	8/22/97 98ZZZX1153
ENGINE FAILED SB LT101-72-10-0153. EXCESSIVE IBPT BLADE SHIFT Q-ROTOR = 6.77 GMIN2. REPLACED WITH NEW UNIT, CORRECTED PROBLEM. PART TC: 3,128.1.									

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
7250 R7MA	586BH 7129	BOLKMS BK117A4	LYC LTS101650B1			BEARING 430102301	PITTED RT ENGINE	756	8/22/97 98ZZZX1152
RIGHT ENGINE BEARING HAS EXCESSIVE PITTING. REPLACED WITH NEW UNIT, CORRECTED PROBLEM.									
7314	736XB R1722860	CESSNA R172K	CONT IO360K			FUEL PUMP 6467592	DEFECTIVE STOP PIN	2000	3/1/98 98ZZZX1176
IN-FLIGHT MIXTURE CONTROL WOULD STICK AND WOULD NOT GO BACK TO FULL RICH MIXTURE. PREVIOUSLY, MOISTURE STIFF BUT WOULD MOVE, AND INSPECTION FOUND NO PROBLEMS. AFTER LAST 'STICK', INSPECTION FOUND THAT IDLE CUT-OFF STOP PIN WAS LOOSE IN ITS HOLE AND FREE TO MOVE IN AND OUT OF ITS HOLE FAR ENOUGH TO BLOCK MIXTURE LEVER. REPLACED PUMP WITH NEW PART.									
8530	99295 17276429	CESSNA 172P	LYC O320D2J			CYLINDER NR 1	FAILED NR 1	1620	12/13/97 98ZZZX1127
FOLLOWING 45 MINUTES OF FLIGHT, ENGINE BECAME ROUGH. CARBURETOR HEAT APPLIED, BUT ROUGHNESS THE SAME. APPLIED FULL POWER AND RETURNED AND ON SHORT FINAL, TOWER REPORTED HEAVY SMOKE. INSPECTION FOUND ENGINE HAD ONLY 3 QUARTS OF OIL LEFT. NR 1 CYLINDER PISTON NICKED AND HEAD CRACKED.									
7420	974SG 18280083	CESSNA 182S	LYC IO540*		SLICK	HARNESS	DAMAGED ENGINE IGNITION	35	3/2/98 98ZZZX1104
DURING TROUBLESHOOTING, ROUGH MAG DROP DISCOVERED DURING RUN-UP. DISCOVERED NYLON TIE WRAPS HOLDING IGNITION HARNESS LEADS TOGETHER IN BUNDLES SO TIGHT THE LEADS WERE DISTORTED. IGNITION LEADS WERE DISCOVERED STRETCHED TIGHT BETWEEN ENGINE AND MOUNT. FAULT DISCOVERED TO BE WHERE A NYLON TIE WRAP HAD CHAFED THROUGH SHIELDING AND BROKEN INNER INSULATION OF ONE IGNITION LEAD ALLOWING LEAD TO SHORT DURING OPERATION. OTHER LEADS DISCOVERED DAMAGED. SUBMITTER FEELS SERIOUS PROBLEM EXISTS SINCE LEAD FAILED WITH EXTREME LOW TIME IN SERVICE.									
7324	3246M 402C0294	CESSNA 402C	CONT TSIO520UB			LINE 5200106101	FAILED FLOW DIVIDER		2/1/98 98ZZZX1125
FUEL REF LINE FROM FLOW DIVIDER TO BAFFLE BROKE CAUSING A ROUGH RUNNING ENGINE. AIRCRAFT LANDED WITHOUT INCIDENT.									
8550	39058 AA1C0206	GULSTM AA1C	LYC O235L2C			LINE MILH6000	BLOCKED OIL BREATHER		2/12/98 98ZZZX1142
ENGINE BEGAN LEAKING OIL AT CYLINDER THRU STUD LOCATIONS. AT SAME TIME, FUEL PRESSURE ROSE APPROX 2 POUNDS. FOUND BREATHER LINE MIL-H-6000, .75 INCH TUBE, BLOCKED APPROX 95 PERCENT. BLOCKAGE APPEARS TO BE DETERIORATED INNER HOSE MATERIAL. HOSE MFG'D IN 1973. ACFT MFG'D IN 1978. HOSE WAS OLD AT TIME OF INSTALLATION. SUBMITTER RECOMMENDED CHANGING ALL RUBBER HOSES EVERY 5 YEARS AND INSPECTING ID OF BREATHER HOSE AT ANNUAL. PRESS BUILD-UP IN THE CRANKCASE CAN CAUSE LOSS OF ENGINE PROPELLER NOSE SEAL AND SUBSEQUENT LOSS OF ALL ENGINE OIL. HIGHER THAN NORMAL FUEL PRESSURE CAN CAUSE FLOODING OF CARBURATED ENGINE. POOR CRANKCASE BREATHING CAN ALSO CONTRIBUTE TO ACCELERATED CORROSION.									
7322	550JM 0013E	HUGHES 369E	ALLSN 250C20B		BENDIX 23057344	FUEL CONTROL 252464429	MALFUNCTIONED ENGINE		2/23/98 98ZZZX1147
ENGINE STILL HAVING DELAYED STARTS. ENGINE FLAMED OUT AT IDLE. RESTARTED WITH THE START PUMP ON, AND FLAMED OUT DURING THE START SEQUENCE. RESTARTED AGAIN, MADE IT TO IDLE, BUT FLAMED OUT AGAIN. REMOVED THE FUEL CONTROL AND INSTALLED A DASH 28 UNIT. NO FURTHER PROBLEMS. TIME ON FUEL CONTROL SN 310785 WAS 1237.5 HOURS TSO, AND 31.6 HOURS SINCE REPAIR.									
7323 JP0M	50AP 1090585D	HUGHES 369D	ALLSN 250C20B		BENDIX 23057870	FLYWEIGHT BUSH 2539034	WORN N2 GOVERNOR		2/10/98 98ZZZX1026
PILOT EXPERIENCED DROOP OF N2 RPM (ROTOR) TO 100 PERCENT. BEEFED UP TO 102 PERCENT, THEN N2 RPM WENT UP TO 104 PERCENT. ERRATIC OPERATION NOTICED. RETURNED GOVERNOR TO REPAIR STATION FOR REPAIR AND REINSTALLED. PROBLEM CORRECTED.									
8520 Q2AR	73N 230	PARTEN P68C	LYC IO360A1B6			STUD 5015	FAILED NR 2 CYL BASE		3/5/98 98ZZZX1109
DURING 100-HOUR INSPECTION, NR 2 CYLINDER BASE STUD FOUND BROKEN. SUBMITTER SUGGESTED POSSIBLY CAUSED BY ENGINE TOTAL TIME.									

***** DENOTES SIGNIFICANT OCCURRENCE

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
7314	37AT	PIPER	LYC			PUMP	LEAKING	17	3/10/98
ODAR	4636135	PA46350P	TIO540AE2A			RG9080J4A	ENGINE FUEL		98ZZZX1131
OWNER NOTICED FUEL STAIN ON BELLY OF NEW AIRCRAFT. AFTER INVESTIGATION, FOUND THAT ENGINE DRIVEN FUEL PUMP SEAL HAD EXTRUDED AND FUEL WAS LEAKING. LOG BOOKS INDICATED THE SCREWS HOLDING THE CAP AND SEAL IN PLACE HAD BEEN TORQUED IAW LYCOMING SB 529. ALL SCREWS WERE LYCOMING SAFTIED, BUT SCREWS WERE FOUND FINGER TIGHT. NEW FUEL PUMP WAS INSTALLED CORRECTING PROBLEM.									

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES)

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS**3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2312 HEEA	10761 45381	BELL 206L1			RT13	TRANSCEIVER 4000102000	FAILED COCKPIT		3/18/98 HEEA0013374
NO 5 VOLTS OUT OF POWER SUPPLY AND CHECK TONES FOR PROPER OPERATION.									
2562 HEEA	513EH 45421	BELL 206L1			NARCO	ELT ELT910	DEFECTIVE COCKPIT		3/4/98 HEEA0013272
NARCO ELT BATTERY WEAK.									
3416 HEEA	3207Q 51540	BELL 206L3				ALT ENCODER A30	FAILED COCKPIT		3/18/98 HEEA0013386
ENCODER HAS NO VALID OUTPUT.									
3421 HEEA	42EA 51542	BELL 206L3				ATTITUDE GYRO 206075607103	FAILED COCKPIT		3/18/98 HEEA0013395
ATTITUDE GYRO PRECESSES AND WILL NOT CAGE.									
3424 HEEA	2251Z 45756	BELL 206L1				INDICATOR A593002	FAILED COCKPIT T&B		3/18/98 HEEA0013396
T&B INDICATOR IS NOT WORKING.									
3424 HEEA	6251V 51404	BELL 206L3				INDICATOR 206070274005	FAILED COCKPIT T&B		3/18/98 HEEA0013397
INDICATOR "DEAD" IS INOPERATIVE AND NEEDS LIGHT.									
3453 HEEA	513EH 45421	BELL 206L1			KA83	ANTENNA 071143100	FAILED LORAN		3/18/98 HEEA0013372
LORAN HAS NO SIGNAL WITH THIS ANTENNA. BAD FROM STOCK.									
3442 HEEA	102PH 30899	BELL 212			P40001	INDICATOR MI5852013	FAILED COCKPIT		3/18/98 HEEA0013361
THE CONTRAST IS NOT BRIGHT ENOUGH TO READ THE SCREEN. THERE IS ONLY ONE COLOR. VERIFIED, FOUND INTENSITY KNOB TURNED DOWN, ALSO FOUND YELLOW DISPLAY PROBLEM ON MEMORY BOARD. REPLACED IC15, U1011, U1017, U1015, U1014, U1008, U1009. REPAIRED. BENCH CHECK GOOD.									
3424 HEEA	3893L 33006	BELL 412				RATE GYRO 214075244001	ERRATIC COCKPIT		3/18/98 HEEA0013392
RATE GYRO ERRATIC INDICATION.									
3424 HEEA	6559Z 36019	BELL 412				RATE GYRO 214075244001	FAILED COCKPIT		3/18/98 HEEA0013393
RATE GYRO INOPERATIVE.									
3452 HEEA	6559Z 36019	BELL 412				CONTROL 071119218	FAILED COCKPIT		3/18/98 HEEA0013373
TRANSPONDER DOES NOT TEST PROPERLY AND NO LIGHTS TO SHOW MODE IT IS IN.									
3416 HEEA	967MB S737	BOLKMS BO105S				ALT ENCODER A30	FAILED COCKPIT		3/18/98 HEEA0013385
ALT ENCODER HAS NO VALID OUTPUT.									

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2562	5532H 111035	PIPER PA11				ELT EBC102A	FAILED COCKPIT		12/31/97 98ZZZX1179
THE ELT DID NOT ACTIVATE ON IMPACT. IT DID TEST USING AN AM RADIO AFTER TURNING ON MANUALLY. THE DATE ON THE BATTERY WAS DUE DECEMBER, 1993.									
6113 WIWR	22JL 347250198	PIPER PA34200		HARTZL HCC2YK2		BULKHEAD 453978	CRACKED PROPELLER		3/18/98 98ZZZX1180
AFTER FAILURE OF PROPELLER SPINNER BULKHEAD ON SIMILAR MODEL AIRCRAFT, CLOSE INPSECTION COMPLETED WITH DYE PENETRANT, FOUND CRACKS PROGRESSING FROM PROP SPINNER BULKHEAD MOUNTING BOLT HOLES. SUSPECT REASON FOR PREMATURE FAILURE IS WRONG LENGTH OF SCREW USED ON SPINNER. IF NEXT SIZE LONGER SCREW IS USED OTHER THAN CALLED FOR, IT WILL RESULT IN PRELOADING SPINNER BULKHEAD TO ENGINE DAMPENER DYNAMIC BALANCER) WHERE IT BOTTOMS OUT. RECOMMEND INSPECTING FOR CORRECT LENGTH OF SCREWS AND USING EITHER MAGNIFYING GLASS OR DYE PENETRANT FOR INSPECTION. CRACKS WERE FOUND ON BOTH RIGHT AND LEFT PROPS.									
3120	4055L 2916	SNIAS AS350B2				RELAY V23154C0721GB104	FAILED HOBBS METER		2/15/98 98ZZZX1116
DISCREPANCY IN THE HOUR METER. TIME WAS LESS THAN ACTUAL FLIGHT TIME. T/S OF THE METER REVEALED THERE WAS NO POWER AVAILABLE TO HOBBS METER. DISCOVERED THE RELAY WAS HALF FILLED WITH WATER AND THE PINS IN THE SOCKET HAD RUSTED OFF. UPON EVALUATING THE FAILURE NOTED THE RELAYS ARE NOT SEALED, AND EACH RELAY IS INSERTED IN A SOCKET WHICH CONTRIBUTES TO POOR CONTACT AND THE POTENTIAL FOR CORROSION. THE LOCATION OF THE RELAYS IS SUCH THAT THE AIR CONDITIONING CONDENSATION WILL AMOST CERTAINLY DRIP ON THE RELAYS. SOLUTION WOULD BE TO INSTALL HERMETICALLY SEALED RELAYS J2K-4730-107P OR EQUIVALENT AND MOUNT THEM TO THE PANEL NEXT TO THE HOUR METER.									

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS)

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS


3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
6114	6624C	CESSNA		MCAULY		HUB	CRACKED		2/27/98
	414A0034	414A		3AF32C93		C93	NR 2 SOCKET		98ZZZX1130
AFTER TEAR-DOWN, A CRACK WAS FOUND IN NR 2 BLADE SOCKET ON THE ENGINE SIDE.									

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS)



INTERNATIONAL SERVICE DIFFICULTY REPORT



INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT**3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
3210		AMTRMX XP503	AMTR 582			LANDING GEAR	DAMAGED MAIN LANDING GEA		1/20/98 AU980098
(AUS) AIRCRAFT HIT FENCE WHEN CONTROL LOST DURING LANDING. DAMAGE CAUSED TO LANDING GEAR, NOSE POD AND LOWER FUEL TANK. THIS DEFECT WAS RECEIVED FROM THE AUF AND IS FOR INFORMATION ONLY.									
5730		BEECH 58	CONT IO520C	MCAULY 3AF34C502	BEECH 585301565	COVER 58530158	SEPARATED WING SPAR		1/19/98 AU980061
(AUS) LH SPAR COVER SEPARATED AND JAMMED BETWEEN LANDING GEAR MICROSWITCHES.									
2430		BEECH 65A90	PWA PT6A20			ELECT POWER	LOSS DC SYS	679	5/6/93 CA930527205
(CAN) 10-20 MINUTES AFTER A LIGHTNING STRIKE, THE AIRCRAFT EXPERIENCED A TOTAL LOSS OF ELECTRICAL POWER. PILOT UNABLE TO RESTORE ANY SYSTEM WITH GENERATOR OR BATTERY. BATTERY VOLTAGE AT 12V. BATTERY RECHARGED AND START/GEN REPLACED. UNABLE TO DETERMINE CAUSE.									
5711		BNORM BN2A26	LYC O540E4C5	HARTZL HCC2YK2		WEB	CRACKED LT WING SPAR		1/28/98 AU980071
(AUS) LH WING SPAR WEB CRACKED BEYOND LIMITS.									
5711		BNORM BN2A26	LYC O540E4C5	HARTZL HCC2YK2		WEB	CRACKED RT WING SPAR		1/29/98 AU980072
(AUS) LH AND RH SPAR WEBS CRACKED BEYOND LIMITS.									
2910		CESSNA 402C	CONT TSIO520VB	MCAULY 3AF32C505		HOSE AE1003757G0310	DETERIORATED HYDRAULIC MAIN		1/22/98 AU980069
(AUS) HYDRAULIC PRESSURE HOSE LOCATED BETWEEN RH HYDRAULIC PUMP AND FIREWALL DAMAGED AND LEAKING. LANDING GEAR WOULD NOT EXTEND AND AIRCRAFT LANDED WITH GEAR UP. INVESTIGATION FOUND THAT THE HOSE FAILED DUE TO EXPOSURE TO HEAT WITH THE FIRE SLEEVING AND THE OUTER HOSE CASE BURNED THROUGH DUE TO POSITIONING ON THE RH ENGINE EXHAUST PIPE STAINLESS STEEL SHROUD WHICH WAS TOUCHING THE EXHAUST PIPE.									
2910		CESSNA 402C	CONT TSIO520VB	MCAULY 3AF32C505	CESSNA 402C	PIPE 520010789	CORRODED HYD MAIN		1/30/98 AU980091
(AUS) RH MAIN LANDING GEAR RETRACTION SYSTEM HYDRAULIC PIPE LOCATED IN AREA BELOW THE RH FLOOR CONTAINED PITTING CORROSION. SUSPECT DUE TO CONTACT WITH DUCTING INSULATION.									
2435		DHAV DHC6300	PWA PT6A27		LUCAS 23048004	BEARING 9204SSX10	UNAPPROVED START/GEN		12/18/97 987 CA971231025
*****	(CAN) INSPECTION FOUND THAT THE BEARINGS WERE UNAPPROVED FOR THIS INSTALLATION. THE BEARING FOUND WAS MANUFACTURED BY BARDEN. ONLY LUCAS BEARINGS P/N 03-6010-18 SHOULD BE USED. THERE WAS ALSO A BRASS SHIM BETWEEN THE DRIVE SHAFT AND THE DAMPER HUB ALLOWING THE HUB TO SIT LOWER DOWN ON THE SHAFT. THIS IS ALSO AN UNAPPROVED PRACTICE. IN ADDITION, THE FRONT END BELL LINER WAS NOT REPAIRED PER APPROVED SPECS.								
3320		DHAV DHC6100	PWA PT6A20			CIRCUIT BREAKER D727185	FUSED COCKPIT OVERHEAD		12/12/97 CA971231030
(CAN) WHEN GROUND POWER APPLIED, AND CABIN LIGHTS SELECTED ON, SMOKE WAS OBSERVED COMING FROM THE OVERHEAD CIRCUIT BREAKER PANEL. WIRING FOR THE LEFT HAND CABIN LIGHTS DIM WAS FOUND COMPLETELY BURNT. THE 5 AMP CIRCUIT BREAKER WAS FUSED IN THE CLOSED POSITION. THE CB COULD NOT TRIP AND THE FIRST DIM LIGHT SOCKET WAS SHORTED CAUSING THE PROBLEM. SEVERAL SOCKETS WERE REPLACED BECAUSE OF CORROSION AND BAD CONNECTIONS. SUBMITTER SUSPECTS THAT THE CB PROBLEM MAY HAVE BEEN CAUSED BY REPEATED RESETTNG OF IT IN-FLIGHT.									
3260		EMB EMB110P1	PWA PT6A34	HARTZL HCB3TN3		SWITCH MS272402	FAILED LANDING GEAR POS		1/23/98 AU980089
(AUS) LH MAIN LANDING GEAR DOWN MICROSWITCH FAULTY.									

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
5711		GULSTM 500B	LYC IO540E1B5	HARTZL HCA3VK4		STRAP	CRACKED WING SPAR STRUCT		1/3/98 AU980081
(AUS) LH WING UPPER SPAR STRAP CRACKED. RH WING LOWER SPAR STRAP ALSO CRACKED. FOUND DURING INSPECTION IAW SB 223.									
2731		PIPER PA31350		HARTZL HCE3YR2		ACTUATOR 17088000	WORN ELEVATOR TAB CON		2/5/98 AU980103
(AUS) ELEVATOR TRIM ACTUATOR WORN. ILLEGAL METAL SHIM INSTALLED BETWEEN THE ACTUATOR DRUM AND THE DRUM HOUSING. PERSONNEL/MAINTENANCE ERROR. UNAPPROVED PART.									
2842		PIPER PA31	LYC TIO540A2B	HARTZL HCE3YR2		TRANSMITTER 4064802030405	DEFECTIVE FUEL QUANTITY		1/15/98 AU980082
(AUS) FIVE OUT OF EIGHT FUEL QUANTITY TRANSMITTERS WERE FAULTY WITH RESISTANCE VALUES OUT OF LIMITS.									
3210		PIPER PA31350		HARTZL HCE3YR2		LANDING GEAR	WORN LANDING GEAR SYS		2/5/98 AU980106
(AUS) LH, RH AND NOSE LANDING GEAR TRUNNIONS, LINKS, ROD AND ACTUATOR BEARINGS AND BUSHINGS WORN BEYOND LIMITS. ALL LANDING GEARS HAVE EXCESSIVE WEAR AND PLAY.									
3222		PIPER PA31350		HARTZL HCE3YR2		PISTON 4533303	WORN NLG OLEO		2/5/98 AU980100
(AUS) NOSE LANDING GEAR OLEO PISTON CHROME PLATING WORN. SIZE OF WORN AREA APPROXIMATELY 50.8MM (2IN) IN DIAMETER.									
3222		PIPER PA31350		HARTZL HCE3YR2		TRUNNION 40273000	DAMAGED NOSE GEAR		2/5/98 AU980099
(AUS) NOSE LANDING GEAR TRUNNION DEFORMED IN AREA OF NOSE WHEEL STEERING LOCK/STOP. CRACKING STARTING TO DEVELOP ON THE INSIDE EDGE OF THE STOP.									
3233		PIPER PA31350		HARTZL HCE3YR2	WIEBEL 21151	ACTUATOR 757499	BROKEN MLG ACTUATOR		2/5/98 AU980102
(AUS) MAIN LANDING GEAR ACTUATOR SHAFT BROKEN. RAM ADJUSTMENT STOP HAS BEEN ILLEGALLY MODIFIED WITH THE PLAIN NUT REPLACED WITH A METALLOCKNUT AND THE REMAINING LOCKING NUT NOT LOCKWIRED. UNAPPROVED PART. PERSONNEL/MAINTENANCE ERROR.									
3252		PIPER PA31350		HARTZL HCE3YR2		DAMPER 2170105	CORRODED SHIMMY DAMPER		2/5/98 AU980101
(AUS) NOSE LANDING GEAR SHIMMY DAMPER PISTON CORRODED AND CHROME PLATING RUSTED OFF. SHIMMY DAMPER ALSO LOW ON OIL.									
5280		PIPER PA31350		HARTZL HCE3YR2		DOOR 475293031	CRACKED RT MLG		2/5/98 AU980109
(AUS) LH AND RH MAIN LANDING GEAR FLIPPER DOORS EXTENSIVELY CRACKED.DOORS HAD BEEN PREVIOUSLY REPAIRED.									
5311		PIPER PA31350		HARTZL HCE3YR2		FRAME 4105008	CRACKED DOOR SUPPORT		2/5/98 AU980108
(AUS) CABIN DOOR HINGE SUPPORT FRAME FAILED CAUSING THE DOOR SILL AND FLOOR SKIN TO CRACK. SUSPECT CAUSED BY ILLEGAL USE OF CHAINS FOR THE DOOR SUPPORT INSTEAD OF CABLE AND TURNBARREL ASSEMBLY.UNAPPROVED PART.									
5320		PIPER PA31350		HARTZL HCE3YR2		FRAME 43179001	CRACKED RUD TORQ TUBE MT		2/5/98 AU980105
(AUS) RUDDER PEDAL TORQUE TUBE CENTRE MOUNT SEPARATED FROM THE CENTRE CONSOLE ASSEMBLY.									

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
5510		PIPER PA31350		HARTZL HCE3YR2	PIPER 40155	HINGE 42235	CRACKED HORIZONTAL STAB		1/5/98 AU980084
(AUS) HORIZONTAL STABILISER OUTBOARD HINGE BRACKETS CRACKED.									
5523		PIPER PA31350		HARTZL HCE3YR2	PIPER 4042009	BRACKET 4042010	CRACKED ELEV TAB HINGE		1/23/98 AU980085
(AUS) ELEVATOR TRIM TAB HINGE BRACKETS PNO 4042-010, PNO 4042-009 AND PNO 4042-008 CRACKED.									
5710		PIPER PA31350		HARTZL HCE3YR2		FRAME 454490809	CRACKED LT RT WING		2/5/98 AU980107
(AUS) LH AND RH WING ARCH FRAMES CONTAIN NUMEROUS CRACKS. LONGEST CRACK IS MORE THAN 127MM (5IN) IN LENGTH. CAUSED BY CONTACT WITH BRAKE CYLINDERS.									
5751		PIPER PA31350		HARTZL HCE3YR2		BEARING 452386	WORN LT RT AIL HINGE		2/5/98 AU980111
(AUS) LH AND RH AILERON HINGE BEARINGS WORN.									
5753		PIPER PA31350		HARTZL HCE3YR2		FLAP 4018543	CORRODED TE FLAP STRUCTUR		2/5/98 AU980104
(AUS) RH FLAP LEADING EDGE SKIN SEPARATED OVER A LENGTH OF 203.2MM(8IN) IN AREA BEHIND ENGINE DUE TO CORROSION AND RIVET FAILURE.									
8120		PIPER PA31350	LYC TIO540J2BD	HARTZL HCE3YR2		BLANKET 452939	BURNT LT RT EXH TURBO		2/5/98 AU980110
(AUS) LH AND RH ENGINE TURBOCHARGER INSULATION BLANKETS DETERIORATED AND BURNT.									

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT)

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS**3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
6330		AEROSP AS355F1	ALLSN 250C20F		355A32060001	SUSPENSION BAR 355A38004004	DEBONDED BEARING	456	10/25/97 CA971110017
(CAN) ON DAILY INSPECTION IT WAS NOTED THAT RIGHT SIDE TRANSMISSION FORWARD SUSPENSION BAR AND THE AFT RIGHT SIDE SUSPENSION BAR LOWER BEARINGS HAD BECOME DEBONDED FROM THE METAL BAR.									
2121		BELL 206B	ALLSN 250C20B		DYNAMICAIR	BLOWER C241500E	VIBRATING CABIN	11/12/97 4	CA971216042
(CAN) CASEY BLOWER MOTOR HAD EXCESSIVE VIBRATION AFTER OVERHAUL.									
3040		BELL 206B	ALLSN 250C20			BLOWER 2060704755	FAILED DEFOG	9/16/97 3	CA971113058
(CAN) DEFOG BLOWER MADE A CLANGING NOISE AND THEN QUIT.									
6220		BELL 206L1	ALLSN 250C28B		206011100025	BUFFER PAD GD80172	DISBONDED M/R GRIP	4531	10/10/97 CA971113046
(CAN) ROTOR HEAD ASSEMBLY RECEIVED FROM VENDOR TSO ZERO HOURS. SAME FOUND BUFFER PAD ON GRIP DEBONDED BY APPROXIMATELY 50 PERCENT.									
6220		BELL 206L1	ALLSN 250C28B		206011100025	GRIP 206011132009	CORRODED M/R HEAD	4533 817	10/6/97 CA971113045
(CAN) CORROSION BEYOND LIMITS FOUND UNDER DEBONDED UPPER BLADE GRIP BUFFER PAD.									
6310		BELL 206B	ALLSN 250C20		206040230025	O-RING	LEAKING INNER SHAFT	10626 647	9/9/97 CA971113047
(CAN) STATIC LEAK OUT OF FRONT PLUG OF FREEWHEEL. PLUG WAS REMOVED AND NEW O-RING INSTALLED. OLD RING WAS DRY AND CRACKED.									
6520		BELL 206B	ALLSN 250C20			GEARBOX 2060404005	PRELOADING T/R	16485 3584	8/25/97 CA971015046
(CAN) TAIL ROTOR GEARBOX PITCH CHANGE SHAFT PRE-LOADING TO ONE SIDE WHEN PITCH CHANGE LINKS ARE TORQUED CAUSING VIBRATION.									
6720		BELL 206B	ALLSN 250C20			SUPPORT ASSEMBLY 206030111003	CORRODED FWD BELLCRANK	17662	10/9/97 CA971113052
(CAN) SEVERE CORROSION FOUND ON AFT LOWER SIDE OF TAIL ROTOR FORWARD CONTROL ROD BELLCRANK SUPPORT.									
6730		BELL 206L1			RONSON 2060760623	BOLT	OVERTORQUED SERVO	9840 867	7/8/97 CA971216037
(CAN) HYDRAULIC SERVO PILOT BOLT FOUND TO HAVE WASHER BOTTOMED ON SHOULDER OF BOLT, SIGNIFYING OVERTORQUE OF THE BOLT.									
7120		BELL 206L	ALLSN 250C20B		206033302103	STIFFENER 206033201163	CRACKED FWD LEFT LEG	11/20/97	CA971208004
(CAN) BOTH STIFFENER AND FRAME CRACKED AND BROKEN OFF AFT OF HOLE STATION 154.50, AT FORWARD LEFT LEG. FRAME CRACKED APPROXIMATELY .75 INCH ON EACH SIDE INBOARD AND OUTBOARD AFT SIDE OF LEFT ENGINE MOUNT ATTACHMENT BOLT. SRM SECTION 5-1-4 HAS REPAIR.									
7310		BELL 206B	ALLSN 250C20			FUEL LINE 6875632	CRACKED ENG FUEL	9/24/97	CA971113048
(CAN) FUEL LEAK FOUND WITH LINE CRACKED AT THE FLARE UNDER THE COLLAR AND "B" NUT. LINE HAD BEEN INSTALLED CORRECTLY.									

**** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
7323		BELL 206B	ALLSN 250C20			GOVERNOR 23006259	FAILED TURB GOV	6361 396	10/30/97 CA971113053
(CAN) ROTOR RPM DROOPS TO 98 PERCENT WITH NO RECOVERY BY GOVERNOR. UNABLE TO ADJUST TO MAINTAIN PROPER RPM. TWO PREVIOUS REMOVALS FOR SAME REASON. PART TC: 2.									
7714		BELL 206B	ALLSN 250C20		206062627003	PLUG	WORN N1 TACH GEN		11/4/97 CA971113054
(CAN) N1 TACH GENERATOR INDICATION INTERMITTENT. CANNON PLUG PIN WORN AND PUSHED IN.									
2910		BELL 212				ELBOW MS21926W6	CRACKED HYD LINE		10/8/97 CA971016020
(CAN) A SLIGHT LEAK AT A HYDRAULIC LINE P/N 212-076-348-1 BECAME WORSE WHEN THE 'B' NUT WAS TIGHTENED. ELBOW WAS FOUND CRACKED IN 2 LOCATIONS ABOUT 180 DEGREES APART. THE CRACKS RADIATED FROM END OF FLARE.									
6210		BELL 212	PWA PT6T3		212040004005	TIP CAP 204012001015	FAILED M/R BLADE		10/22/97 CA971028012
(CAN) TIE DOWN WAS INSTALLED ON FORWARD AND REAR BLADE OF AIRCRAFT DUE TO HIGH WINDS. TIP CAP FAILED DUE TO FLAPPING CAUSED BY HIGH WINDS THEN FORWARD MAIN ROTOR BLADE CONTACTED WIRE STRIKE KIT, CAUSING DAMAGE TO MAIN ROTOR BLADE.									
6310		BELL 212	PWA PT6T3		212040001123	SPIRALBEVEL GEAR 204040701101	CRACKED MATING FLANGE	8914 990	11/6/97 CA971110004
(CAN) IN NORMAL SERVICE, THE ATTACHMENT BOLT TORQUE OF THE GEAR TO SHAFT (P/N 204-040-324-5) BECAME REDUCED RESULTING IN FRETTING CORROSION OF THE MATING SURFACES. A SURFACE CRACK WAS FOUND DURING OVERHAUL BETWEEN TWO OF THE ATTACH BOLT HOLES IN THE GEAR. SUBMITTER SUSPECTS THAT CRACK ONLY EXTENDS THROUGH THE SURFACE HARDENING.									
6310		BELL 212	PWA PT6T3		212040005103	COUPLINGS	NO LUBE M/R DRIVE		11/3/97 CA971113060
(CAN) INSUFFICIENT GREASE IN BOTH DRIVE SHAFT COUPLINGS. IN ADDITION, ONE BOOT WAS FOUND COMPLETELY TORN.									
6730		BELL 212	PWA PT6T3			SERVO 2120760057	MALFUNCTIONING CYCLIC		10/8/97 207 CA971016019
(CAN) FOLLOWING INSTALLATION OF THIS SERVO, THE PILOT REPORTED CONTROL FEEDBACK IN THE CYCLIC CONTROL.									
6510		BELL 407	ALLSN 250C47B		407040001101	BRACKET 407040321101	CRACKED T/R DRIVE	451	11/20/97 CA971210019
(CAN) COMPLYING WITH AD CF-97-19, FORWARD BEARING STARTED TO MAKE NOISE. WHILE REPLACING BEARING, THE BRACKET WAS FOUND CRACKED. PART TC: 630.									
6510		BELL 407		REXNARD		DISC 406040340101	CRACKED NR 7 AFT OUTER	303	10/2/97 CA971021023
(CAN) AS PER AD CF-97-19, INSPECTION OF TAIL ROTOR DRIVE SHAFT THOMAS COUPLINGS CARRIED OUT. THE AFT OUTER DISC OF THE NR 7 DISC PACK WAS FOUND BROKEN IN TWO PLACES. DISC PACKS TAKEN FOR TESTING BY BELL. BHTC IS REDESIGNING DISCS TO OVERCOME MID-SPAN CRACKING.									
2551		BOLKMS BO105C	ALLSN 250C20B			CARGO HOOK AZ5LT	FAILED SLING LOAD		10/23/97 CA971119007
(CAN) CARGO HOOK INADVERTENTLY RELEASED SLING LOAD IN-FLIGHT. ON TESTING CIRCUIT, IT TRIPPED THE CIRCUIT BREAKER. ON ONE OCCASION THE HOOK WOULD NOT RELEASE DURING TEST.									
6310		BOLKMS BO105S			4638001001	BEARING 4619303081	PEELING MAIN XMSN		10/6/97 852 CA971024010
(CAN) MAIN TRANSMISSION LEFT INTERMEDIATE SHAFT BEARING FOUND PEELING.									

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
6320		BOLKMS BO105C	ALLSN 250C20B			TRANSMISSION 4638001001	FAILED M/R GR BOX	5968 1984	10/8/97 CA971020017
(CAN) METAL PARTICLES ON MAGNETIC CHIP PLUG OF SIZE AND QUANTITY DEEMED UNACCEPTABLE BY THE MANUFACTURER.									
6410		BOLKMS BO105C	ALLSN 250C20B			BLADE 10531754	ERRODED TAIL ROTOR	2600	10/8/97 CA971020018
(CAN) HOLE ERODED THROUGH LEADING EDGE OF TIP CAP.									
6220		HUGHES 369E	ALLSN 250C20B			FAIRING 369D2100411	SEPARATED MAIN ROTOR HEAD		1/17/98 AU980097
(AUS) MAIN ROTOR HEAD FAIRING (CHINAMANS HAT) SEPARATED FROM AIRCRAFT.SUSPECT FAIRING DEVELOPED A CRACK ALLOWING THE FAIRING TO FLEX AND LOOSEN THE ATTACHMENT SCREWS.									
6410		HUGHES 369D	ALLSN 250C20B			BLADES 369D2161311N	DELAMINATED T/R	2910 130	10/29/97 CA971125004
(CAN) LEADING EDGE STRIP OF BOTH TAIL ROTOR BLADES DEBONDING. DEBONDING OCCURRED IN SAME AREA ON BOTH BLADES.									
6710		HUGHES 369D	ALLSN 250C20B			SWITCH A218100646	FAILED CYCLIC TRIM		10/20/97 CA971113041
(CAN) CYCLIC TRIM SWITCH FAILED CAUSING A HARD LEFT TRIM MOTOR RUN AWAY.									
7323		HUGHES 369D	ALLSN 250C20B		BENDIX	GOVERNOR 23057869	FAILED TURBINE		10/3/97 CA971113032
(CAN) GOVERNOR ALLOWS RPM TO DROOP 3 PERCENT WITH NO RECOVERY AND OVERSPEEDS 2 TO 3 PERCENT. ERRATIC OPERATION, OCCASIONAL SURGING, RIGGING COULD NOT ADJUST.									
7910		HUGHES 369D	ALLSN 250C20B			BOOT	SPLIT OIL TANK		11/28/97 CA971216039
(CAN) RUBBER BOOT CONNECTING THE ENGINE OIL TANK TO THE AIRFRAME FILLER NECK SPLIT UNDER THE ATTACHING CLAMP CAUSING THE LOSS OF 1.5 LITRE OF OIL.									
6210		SKRSKY S58ET	PWA PT6T6			BLADE S1615203016	DEBONDING M/R	3049	10/21/97 CA971125003
(CAN) DEBONDING OF POCKET FROM MAIN ROTOR BLADE. A SECTION 8 INCHES BY 8 INCHES CAME OFF.									
2913		SKRSKY S61N			66WBL200	BOLTS	BROKEN PUMP END HOUSING		9/29/97 CA971110002
(CAN) THREE OF THE TOTAL OF EIGHT INTERNAL HEX BOLTS WERE FOUND BROKEN. THESE BOLTS GO THROUGH THE END HOUSING OF THE HYD PUMP.									
2435		SNIAS AS350B	TMECA ARRIEL1B		AUXILEC 524031A	SHAFT 1142	SHEARED START/GEN	5891 795	11/9/97 CA971216040
(CAN) DRIVESHAFT SHEARED, SUSPECT ON START. PART TC: 65.									
2435		SNIAS AS350B	TMECA ARRIEL1B		AUXILEC 524031	DRIVE SHAFT 1144	SHEARED START/GEN	6211 932	9/17/97 CA971113037
(CAN) STARTER GENERATOR DRIVE SHAFT SHEARED DURING START.									
2821		SNIAS AS350BA	TMECA ARRIEL1B		PUROLATOR	FUEL FILTER 174364001	FAILED TEST FUEL SYS	297	9/15/97 CA971113044
(CAN) FUEL FILTER ASSEMBLY DID NOT INDICATE BYPASS WHEN PRE-FLIGHT BUTTON PUSHED OR ON DUMMY FILTER INSTALLATION FOR TESTING.									

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2842		SNIAS AS350B	TMECA ARRIEL1B		JAEGER	TRANSMITTER 647510033	FAILED FUEL QTY	86	8/8/97 CA971015042
(CAN) NO FUEL QUANTITY INDICATION. RESISTANCE CHECK OUT OF LIMITS.									
2913		SNIAS AS350B	TMECA ARRIEL1B			PUMP 350A35013504	OVERHEATED BEARINGS		10/18/97 CA971113057
(CAN) BEARINGS VERY TIGHT AND NOISY, AND RUNNING HOT. CAUSED DAMAGE TO THE HYDRAULIC PUMP DRIVE BELT P/N 704-A33-690-004.									
2930		SNIAS AS350BA	TMECA ARRIEL1B			SWITCH NE15FBAT	MISWIRED HYD SYS	2563	10/19/97 CA971104013
(CAN) HYDRAULIC CUT-OFF SWITCH WAS MISWIRED TO WARNING HORN, BUT FUNCTIONED PROPERLY IN THE HYDRAULIC CUTOFF MODE. RE: SB 29.01. PART TC: 692.									
3040		SNIAS AS350B	TMECA ARRIEL1B			HOSE 350A72072102	RUPTURED DEFROST	9831	9/9/97 CA971015048
(CAN) DEFROST HEATER HOSE DETERIORATED AND BLEW APART MELTING THE FIRST AID KIT.									
3422		SNIAS AS350B	TMECA ARRIEL1B			DIRECTIONAL GYRO 200DC	FAILED COCKPIT DG	24	10/30/97 CA971216038
(CAN) DIRECTIONAL GYRO SPINS CONTINUOUSLY AND VERY RAPIDLY.									
3422		SNIAS AS350B	TMECA ARRIEL1B			CASING 5050010902	BROKEN COCKPIT DG	486	9/15/97 CA971015051
(CAN) BACK CYLINDRICAL PIECE OF DIRECTIONAL GYRO FOUND HANGING BY INTERNAL WIRING. MOUNTING HARDWARE RATTLING AROUND ON INSIDE.									
6520		SNIAS AS350B2				GEARBOX 350A33020004	FAILED TAILROTOR	8246 1002	10/15/97 CA971028009
(CAN) TAIL ROTOR GEARBOX MAGNETIC CHIP DETECTOR ILLUMINATED DURING CRUISE JUST AFTER TAKEOFF. A LOT OF SHAVINGS AND CHIPS FOUND. PLUG CLEANED. AIRCRAFT RUN-UP, SHUTDOWN AND CHECKED. MORE METAL FOUND. GEARBOX SENT FOR CHECK.									
6710		SNIAS AS350BA	TMECA ARRIEL1B			FRICTION CUP 350A27161220	DEFECTIVE CYCLIC LOWER	268	10/10/97 CA971021012
(CAN) PILOT REPORTED CYCLIC CONTROLS WERE BINDING WHEN FRICTION KNOB WAS TURNED TO APPLY FRICTION. OK WITHOUT FRICTION. LOWER CUP NOT PERFECTLY ROUND. SURFACE REWORKED.									
6730		SNIAS AS350B	TMECA ARRIEL1B		DUNLOP	SERVO AC67246	LEAKING M/R	453 229	9/16/97 CA971113035
(CAN) SERVO LEAKING AN EXCESSIVE AMOUNT OF OIL.									
7410		SNIAS AS350B	TMECA ARRIEL1B			HE GENERATOR ABG676000	FAILED ENG IGN		8/15/97 CA971015043
(CAN) HIGH ENERGY GENERATOR INSTALLED TO CORRECT INTERMITTENT IGNITION PROBLEM. PROBLEM PERSISTED. NEW GENERATOR WAS FAULTY.									
6320		SNIAS AS332L	TMECA MAKILA1A			SLEEVE 332A32100701	CRACKED M/R GR BOX		10/14/97 CA971121004
(CAN) FRENCH AD T97-303-066, REQUIRED INSPECTION OF THE SLEEVE, SPLINED SHAFT. INSPECTION INCLUDED A DYE PENETRANT OF SHAFT WHICH DETECTED TWO SMALL WEAR MARKS ON THE FRONT OF THE SHAFT ABOUT 120 DEGREES APART. FURTHER INVESTIGATION FOUND THAT THESE WEAR MARKS REVEALED A NUMBER OF SMALL CRACKS ORIGINATING AT WEAR MARKS AND CONTINUING AFT TOWARD THE SPLINES. PARTS SENT FOR ANALYSIS.									

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS)

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - ENGINES**3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
7200		BEECH 99A	PWA PT6A28			ENGINE	CHIP LIGHT NR 1	12/22/97 519	CA971231005
(CAN) PILOT REPORTED NR 1 ENGINE CHIP DETECTOR LIGHT CAME ON 6 MINUTES AFTER TAKEOFF. THE ENGINE WAS SHUTDOWN AND THE AIRCRAFT RETURNED TO BASE. REMOVAL OF CHIP DETECTOR REVEALED A LARGE PIECE OF METAL ACROSS THE LUGS. THE ENGINE WAS A LOANER AND WAS RETURNED TO THE OVERHAUL FACILITY FOR DISPOSITION. THE ENGINE HAS NOT BEEN SPLIT TO DETERMINE THE SOURCE OF THE METAL. PART TC: 718.									
7310		BELL 206B	ALLSN 250C20			FUEL LINE 6875632	CRACKED ENG FUEL	9/24/97 CA971113048	
(CAN) FUEL LEAK FOUND WITH LINE CRACKED AT THE FLARE UNDER THE COLLAR AND "B" NUT. LINE HAD BEEN INSTALLED CORRECTLY.									
7323		BELL 206B	ALLSN 250C20			GOVERNOR 23006259	FAILED TURB GOV	6361 396	10/30/97 CA971113053
(CAN) ROTOR RPM DROOPS TO 98 PERCENT WITH NO RECOVERY BY GOVERNOR. UNABLE TO ADJUST TO MAINTAIN PROPER RPM. TWO PREVIOUS REMOVALS FOR SAME REASON. PART TC: 2.									
8520		CESSNA 150L	CONT O200A		643250	DOWEL 637832	SHEARED STARTER CLUTCH	9/14/97 388	CA971231011
(CAN) ENGINE LOG STATES STARTER CLUTCH WAS CHANGED AT AN UNDETERMINED TIME PRIOR TO THIS FAILURE. THE DOWEL ASSEMBLY THAT RETAINS THE STARTER CLUTCH ADAPTER APPEARS TO HAVE SHEARED. THIS CONDITION ALLOWED THE ADAPTER TO MOVE FREELY IN ITS BORE RESULTING IN GEAR MISALIGNMENT AND SUBSEQUENT PRESSURES THAT FAILED THE CRANKCASE. THE REASON FOR THE DOWEL FAILURE IS UNKNOWN, BUT POSSIBLE INCORRECT INSTALLATION OF THE STARTER CLUTCH ASSEMBLY (P/N 643231) CAUSED THE DOWEL TO FAIL.									
7322		CESSNA 182Q	CONT O470U			CARBURETOR 105284	FAILED ENGINE	12/14/97 923	CA971223011
(CAN) SEVERE CARBURETOR FLOODING ON GROUND RUN-UP, HARD STARTING AND FOULING OF SPARK PLUGS. FUEL WAS SEEN LEAKING FROM THE CARBURETOR. ENGINE FAILED TO SHUTDOWN USING MIXTURE CONTROL AND SEVERE BACKFIRING OCCURRED. THE CARBURETOR WAS REPLACED AND THE PROBLEM WAS ELIMINATED.									
7323		HUGHES 369D	ALLSN 250C20B		BENDIX	GOVERNOR 23057869	FAILED TURBINE	10/3/97 210	CA971113032
(CAN) GOVERNOR ALLOWS RPM TO DROOP 3 PERCENT WITH NO RECOVERY AND OVERSPEEDS 2 TO 3 PERCENT. ERRATIC OPERATION, OCCASIONAL SURGING, RIGGING COULD NOT ADJUST.									
8520		PIPER PA22108	LYC O235C1			CAMSHAFT	WORN ENGINE	12/29/97 855	CA971231022
(CAN) ENGINE CAMSHAFT FOUND WORN. ENGINE CAMSHAFT REPLACED.									
7322		PIPER PA28181	LYC O360A4M	SNSNCH 76EM8	FACET MA45	WASHER 78356	WORN FUEL CARB	2/3/98 AU980075	
(AUS) CARBURETTOR MIXTURE SHAFT RETAINING RING WORN AND LOOSE ALLOWING THE MIXTURE SHAFT TO MOVE FROM ITS NORMAL POSITION. THIS CAUSED A RICH CUT WHEN THE ENGINE WAS BROUGHT BACK TO IDLE FOR LANDING.									

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - ENGINES)

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
2562		BEECH 200BEECH	PWA PT6A41	HARTZL HCB3TN3	E01	BATTERY	LEAKING EMERGENCY LOCATO		1/22/98 AU980064
(AUS) ELT BATTERIES LEAKING. FOUND DURING BATTERY CHANGE.									
3422		SNIAS AS350B	TMECA ARRIEL1B			DIRECTIONAL GYRO 200DC	FAILED COCKPIT DG	24	10/30/97 CA971216038
(CAN) DIRECTIONAL GYRO SPINS CONTINUOUSLY AND VERY RAPIDLY.									
3422		SNIAS AS350B	TMECA ARRIEL1B		5050010902	CASING	BROKEN COCKPIT DG	486	9/15/97 CA971015051
(CAN) BACK CYLINDRICAL PIECE OF DIRECTIONAL GYRO FOUND HANGING BY INTERNAL WIRING. MOUNTING HARDWARE RATTLING AROUND ON INSIDE.									
(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS)									

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS**3/22/98 - 3/28/98 ISSUE: 98-13 ZAC-327**

ATA OPER	REG. NO SERIAL NO	ACFT MAKE ACFT MODEL	ENG MAKE ENG MDL	PROP MAKE PROP MDL	COMP MFG COMP MDL	PART NAME PART NUMBER	PART COND PART LOC.	TT TSO	DIFF. DATE OPER CONT NO
6114		PIPER PA24250	LYC O540A1A5	HARTZL HC82V*		BLADE BEARINGS 790100018	CORRODED PROP	3189 813	12/19/97 CA971231018
(CAN) PROPELLER RECEIVED FOR CORROSION INSPECTION. BLADE BALL BEARINGS AND PILOT TUBE FOUND CORRODED.									
6114		PIPER PA30	LYC IO320B1A	HARTZL HCE2YL2	83021	SCREWS AN501A41610	LOOSE LATCH STOP	1140	12/20/97 CA971231020
(CAN) UPON REMOVAL OF THE PROPELLER CYLINDER FOR PROP OVERHAUL, FOUND 3 OF THE 4 SCREWS (AN501-A416-10) HAD VIBRATED COMPLETELY OFF THE LATCH STOP UNIT WHICH SECURES IT TO THE CYLINDER. THE 4TH SCREW HAD LOCKTITE ON THE SCREW THREADS. BUT THE SCREWS WERE NOT COMPLETELY SECURED TO THE LOCK STOP BASE. TWO OF THE 4 LATCH PINS WERE HOLDING THE PROPELLER BLADES IN THE LATCH POSITION. THE OTHER 2 WERE STUCK IN THE EXTENDED POSITION. THE PITCH STOP BRACKET WAS ALSO DAMAGED.									
6111		PIPER PA31	LYC TIO540A2C	HARTZL HCE3YR2A	HARTZL FC84686R	LOCKING PINS 57A0285	MISSING PROP	494	12/20/97 CA971231019
(CAN) DURING INSPECTION PRIOR TO DECONTAMINATION, FOUND THE COUNTERWEIGHT LOCKING ROLL PINS WERE MISSING ON ALL THREE BLADES (6 BOLTS). ALSO, THE COUNTERWEIGHT BOLTS WERE NOT DRILLED FOR THE 57A0285 ROLL PINS.									
(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS)									



U.S. Department
of Transportation
**Federal Aviation
Administration**

SERVICE DIFFICULTY REPORT SUMMARY

GENERAL AVIATION - INDEX



The following information provides a tally of the Service Difficulty Reports (SDR's) contained in this weeks issue of the General Aviation SDR Summary. The totals represent only a summation of the SDR's that were submitted to the FAA, Aviation Data Systems Branch, AFS-620, and processed in time for inclusion in the Summary. The first table is a tally of the number of SDR's submitted through the indicated Flight Standards District Office (FSDO). The second table sorts the SDR's by the aircraft or equipment make and model. The heading at the top of each table provides a two digit Joint Aircraft System/Component (JASC) code grouping (e.g., JASC codes 1100 thru 1800 are represented by the heading labeled 11-18) which categorizes in general, the problem areas for each reported discrepancy.

The Flight Standards Service Difficulty Program objective is to achieve prompt and appropriate correction of conditions adversely affecting continued airworthiness of aeronautical products. This is accomplished by the collection of Service Difficulty and Malfunction or Defect Reports. SDR's are consolidation and collation into common data base where they are analyzed for trends, problems, and alert information. This information is then disseminated to the appropriate segments of the aviation community and to other FAA offices.

The number of SDR's submitted is not an indicator of the mechanical reliability or fitness of an air carrier's aircraft fleet and should not be used as such. The air carriers certificate holding office has the primary responsibility for planning, programming evaluations, and assessing the performance of operators. Questions regarding an air carrier's fleet performance should be directed to the appropriate Flight Standards District Office, Certificate Management Office, or Certificate Management Unit.

GENERAL AVIATION SUMMARY INDEX BY DISTRICT OFFICE**3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327**

DISTRICT OFFICE		SDR TOTALS BY FAA ATA SYSTEM CHAPTER								TOTAL
		11-18	21-29	30-38	45-49	51-57	61-67	71-79	80-85	
AL	03	0	1	0	0	0	0	1	0	2
AU	S	0	5	7	0	12	1	1	1	27
CA		0	12	5	0	0	26	9	2	54
EA	05	0	1	0	0	0	0	0	0	1
EA	17	0	0	1	0	0	0	0	0	1
EA	21	0	0	0	0	0	0	1	0	1
GL	01	0	1	0	0	0	0	0	0	1
GL	03	0	1	0	0	0	0	0	0	1
GL	19	0	0	0	0	1	0	0	0	1
GL	25	0	0	2	0	3	0	1	0	6
GL	27	0	0	0	0	0	0	1	0	1
NE	01	0	0	0	0	0	1	0	0	1
NE	05	0	0	0	0	0	1	0	0	1
NM	01	0	1	0	0	0	0	0	0	1
NM	03	0	1	0	0	3	1	0	0	5
NM	05	0	0	0	0	1	0	0	0	1
NM	07	0	1	0	0	0	0	1	0	2
NM	09	0	1	1	0	0	0	0	0	2
NM	11	0	0	0	0	1	0	13	0	14
SO	01	0	0	0	0	0	0	1	0	1
SO	03	0	1	1	0	0	0	0	0	2
SO	15	0	1	0	0	0	0	0	0	1
SO	17	0	0	0	0	3	0	0	0	3
SO	19	0	0	0	0	0	1	0	0	1
SO	21	0	0	0	0	0	0	0	1	1
SW	03	0	16	13	0	0	21	9	0	59

DISTRICT OFFICE		11-18	21-29	SDR TOTALS BY FAA ATA SYSTEM CHAPTER						
				30-38	45-49	51-57	61-67	71-79	80-85	TOTAL
SW	05	0	0	0	0	0	1	0	0	1
SW	17	0	0	0	0	1	0	0	1	2
SW	99	0	2	1	0	2	0	0	1	6
WP	07	0	0	0	0	0	1	1	0	2
WP	09	0	0	1	0	0	0	0	0	1
WP	17	0	0	0	0	1	0	0	0	1
WP	19	0	1	0	0	0	0	0	0	1
WP	23	0	0	0	0	0	0	2	0	2
TOTALS		0	46	32	0	28	54	41	6	207

(End of GENERAL AVIATION SUMMARY INDEX by DISTRICT OFFICE Report)

GENERAL AVIATION SUMMARY INDEX by MANUFACTURER MAKE and MODEL**3/22/98 To 3/28/98 ISSUE: 98-13 ZAC-327**

AIRCRAFT MAKE	AIRCRAFT MODEL	SDR TOTALS BY FAA ATA SYSTEM CHAPTER								TOTAL
		11-18	21-29	30-38	45-49	51-57	61-67	71-79	80-85	
AEROSP	AS355F1	0	0	0	0	0	1	0	0	1
AIRTRC	AT502A	0	0	0	0	1	0	0	0	1
AMTRMX	XP503	0	0	1	0	0	0	0	0	1
BBAVIA	7ECA	0	0	0	0	0	0	1	0	1
BEECH	200BEECH	0	1	0	0	0	0	0	0	1
BEECH	58	0	0	0	0	1	0	0	0	1
BEECH	65A90	0	1	0	0	0	0	0	0	1
BEECH	99A	0	1	0	0	0	0	1	0	2
BEECH	F33A	0	1	0	0	0	0	0	0	1
BELL	206B	0	1	1	0	0	3	3	0	8
BELL	206B3	0	1	0	0	0	0	0	0	1
BELL	206L	0	0	0	0	0	0	1	0	1
BELL	206L1	0	2	2	0	0	3	0	0	7
BELL	206L3	0	0	3	0	0	1	0	0	4
BELL	212	0	1	1	0	0	4	0	0	6
BELL	214ST	0	5	0	0	0	1	1	0	7
BELL	230	0	0	0	0	0	9	0	0	9
BELL	407	0	1	1	0	0	4	0	0	6
BELL	412	0	6	3	0	0	3	5	0	17
BELL	OH58A	0	0	1	0	0	0	0	0	1
BNORM	BN2A26	0	0	0	0	2	0	0	0	2
BOEING	1072	0	1	0	0	0	0	0	0	1
BOLKMS	BK117A3	0	0	0	0	0	0	4	0	4
BOLKMS	BK117A4	0	0	0	0	0	0	9	0	9
BOLKMS	BO105C	0	1	0	0	0	2	0	0	3
BOLKMS	BO105S	0	0	1	0	0	1	2	0	4
CESSNA	120	0	0	0	0	3	0	0	0	3

AIRCRAFT MAKE	AIRCRAFT MODEL	SDR TOTALS BY FAA ATA SYSTEM CHAPTER								TOTAL
		11-18	21-29	30-38	45-49	51-57	61-67	71-79	80-85	
CESSNA	150L	0	0	0	0	0	0	0	1	1
CESSNA	172N	0	0	0	0	1	0	0	0	1
CESSNA	172P	0	0	0	0	0	0	0	1	1
CESSNA	182L	0	0	0	0	1	0	0	0	1
CESSNA	182Q	0	0	0	0	0	0	1	0	1
CESSNA	182S	0	0	0	0	0	0	1	0	1
CESSNA	210G	0	0	0	0	1	0	0	0	1
CESSNA	310P	0	0	1	0	0	0	0	0	1
CESSNA	310R	0	1	0	0	0	0	0	0	1
CESSNA	320A	0	0	0	0	2	0	0	0	2
CESSNA	340A	0	0	1	0	3	0	0	0	4
CESSNA	402B	0	1	0	0	0	0	0	0	1
CESSNA	402C	0	2	0	0	0	0	1	0	3
CESSNA	414A	0	1	0	0	0	1	0	0	2
CESSNA	421C	0	0	0	0	1	0	0	0	1
CESSNA	441	0	0	0	0	0	0	1	0	1
CESSNA	A185E	0	0	1	0	0	0	0	0	1
CESSNA	R172K	0	0	0	0	0	0	1	0	1
CESSNA	T210L	0	0	0	0	2	0	0	0	2
DHAV	DHC6100	0	0	1	0	0	0	0	0	1
DHAV	DHC6300	0	1	0	0	0	0	0	0	1
EMB	EMB110P1	0	0	1	0	0	0	0	0	1
ENSTRM	280C	0	0	0	0	0	1	0	0	1
GULSTM	500B	0	0	0	0	1	0	0	0	1
GULSTM	560	0	1	0	0	0	0	0	0	1
GULSTM	AA1C	0	0	0	0	0	0	0	1	1
HUGHES	369D	0	0	0	0	0	2	3	0	5

AIRCRAFT MAKE	AIRCRAFT MODEL	SDR TOTALS BY FAA ATA SYSTEM CHAPTER								TOTAL
		11-18	21-29	30-38	45-49	51-57	61-67	71-79	80-85	
HUGHES	369E	0	0	0	0	0	1	1	0	2
PARTEN	P68C	0	0	0	0	0	0	0	1	1
PIPER	PA11	0	1	0	0	0	0	0	0	1
PIPER	PA22108	0	0	0	0	0	0	0	1	1
PIPER	PA24250	0	0	0	0	0	1	0	0	1
PIPER	PA28140	0	1	0	0	1	0	0	0	2
PIPER	PA28181	0	0	2	0	0	0	2	0	4
PIPER	PA28235	0	1	0	0	0	0	0	0	1
PIPER	PA30	0	0	0	0	0	1	0	0	1
PIPER	PA31	0	1	0	0	0	1	0	0	2
PIPER	PA31310	0	0	0	0	0	1	0	0	1
PIPER	PA31350	0	2	5	0	8	0	0	1	16
PIPER	PA34200	0	0	0	0	0	1	0	0	1
PIPER	PA34200T	0	1	0	0	0	0	0	0	1
PIPER	PA46350P	0	0	0	0	0	0	1	0	1
PIPER	PA60601P	0	1	0	0	0	0	0	0	1
ROBSIN	R44	0	0	0	0	0	2	0	0	2
SKRSKY	S58ET	0	0	0	0	0	1	0	0	1
SKRSKY	S61N	0	1	0	0	0	0	0	0	1
SKRSKY	S76A	0	0	0	0	0	0	1	0	1
SKRSKY	S76C	0	1	0	0	0	0	0	0	1
SNIAS	AS332L	0	0	0	0	0	1	0	0	1
SNIAS	AS350B	0	4	4	0	0	3	1	0	12
SNIAS	AS350B2	0	0	2	0	0	4	0	0	6
SNIAS	AS350BA	0	2	0	0	0	1	0	0	3
TOTALS		0	46	32	0	28	54	41	6	207

(End of AIR CARRIER SUMMARY INDEX by OPERATOR Report)

JOINT AIRCRAFT SYSTEM/COMPONENT CODE TABLE

PREFACE

The Joint Aircraft System/Component (JASC) Code Table is a modified version of the Air Transport Association of America (ATA), Specification 100 code. It was developed by the Federal Aviation Administration's (FAA), Aviation Data Systems Branch (AFS-620). Technical support was provided by the Galaxy Scientific Corporation, and various representatives of the air carrier and general aviation community.

Over the past four years, the JASC format of the ATA Spec 100 code has gained widespread industry acceptance. In a harmonized effort, the FAA's counterparts in Australia and Canada have adopted the JASC code with only a few exceptions. Some Canadian aircraft manufacturers have also recently adopted this new standard.

This code table is constructed by using the new JASC four (4) digit code, along with an abbreviated code title. The abbreviated titles have been modified in some cases to clarify the intended use of the accompanying code. This table can be used as a quick reference chart, to assist in the coding and review of aircraft structures or systems data (i.e., Service Difficulty Report (SDR), Accident/Incident Report).

The current coding scheme used in the JASC code was introduced in May 1991, for the technical classification of SDR's. Its predecessor, the FAA aircraft system/component code, was a similar but more complex eight-digit code which was developed over 25 years ago. It was constructed around the computer technology of that period. It consisted of a four digit numerical code plus a four alpha character code to make data retrieval possible. Since that time, computer technology has advanced many fold. Reducing the code from eight to four characters simplifies coding, and in some cases, makes JASC coding match the ATA Specification 100 first three digits, which are used to identify aircraft systems. The ATA code does not reference the fourth digit, so it is free to be used for identifying components.

The JASC code aircraft structural section has increased due to problems inherent with aging aircraft. As an example, FAA code 5301 SXBD was expanded to 20 items due to the high rate of reporting in this area (8021 structural reports were received in 1989). In some instances, there was very little reporting and codes were combined into other systems if the safety impact was not significant. The overall reduction in codes has been from 568 FAA codes to 488 JASC codes, with the significant increase being in the structural area as stated earlier.

The JASC code divides the engine section into two major code groups to separate the turbine and reciprocating engines. The codes for the turbine engines are in JASC Chapter 72, Turbine/Turboprop Engine. The codes for the reciprocating engines are now exclusively found in JASC Chapter 85, Reciprocating Engine.

The other major deviation from ATA Spec 100 is in ATA section 2730, specifically involves the stall warning system. Early technology (primarily on smaller aircraft) directly linked the sensing of flight attitude to one of the components which furnished the means of manually controlling the flight attitude characteristics (elevator). Today, most large transport category aircraft utilize electronic units to sense the change in the environmental condition called stall, and use the data to influence navigation. ATA section 3410, Flight Environment Data, includes high speed warning in its code definition. Stall warning (low speed) is the reciprocal term of high speed warning, so its filing under the same code appears more logical. Thus, with the JASC code it was decided to move the stall warning system to Chapter 34 under the separate code JASC code 3418, Stall Warning System.

The FAA is continuing to pursue worldwide involvement from operators and manufacturers in addressing the need for international standardization of aircraft system/component codes. The ultimate goal is to develop a universal aircraft/component numbering standard which can be used in the manufacturer's maintenance manual, wiring diagram manual, system manuals and illustrated parts catalog. This harmonized standard must be a usable standard for the aircraft manufacturers, air carrier operators and the general aviation community.

We welcome comments and feedback regarding the possible forming of working groups to achieve this long range consideration of possibly harmonizing the ATA Specification 100 code and the JASC code. Comments may be directed to the FAA, Aviation Data Sytem Branch, AFS-620, P.O. Box 25082, Oklahoma City, OK 73125.

JOINT AIRCRAFT SYSTEM/COMPONENT CODE TABLE

JASC/ TITLE

11 PLACARDS AND MARKINGS

1100 PLACARDS AND MARKINGS

12 SERVICING

1210 FUEL SERVICING
1220 OIL SERVICING
1230 HYDRAULIC FLUID SERVICING
1240 COOLANT SERVICING

18 HELICOPTER VIBRATION

1800 HELICOPTER VIB/NOISE ANALYSIS
1810 HELICOPTER VIBRATION ANALYSIS
1820 HELICOPTER NOISE ANALYSIS

21 AIR CONDITIONING

2100 AIR CONDITIONING SYSTEM
2110 CABIN COMPRESSOR SYSTEM
2120 AIR DISTRIBUTION SYSTEM
2121 AIR DISTRIBUTION FAN
2130 CABIN PRESSURE CONTROL SYSTEM
2131 CABIN PRESSURE CONTROLLER
2132 CABIN PRESSURE INDICATOR
2133 PRESSURE REGUL/OUTFLOW VALVE
2134 CABIN PRESSURE SENSOR
2140 HEATING SYSTEM
2150 CABIN COOLING SYSTEM
2160 CABIN TEMPERATURE CONTROL SYSTEM
2161 CABIN TEMPERATURE CONTROLLER
2162 CABIN TEMPERATURE INDICATOR
2163 CABIN TEMPERATURE SENSOR
2170 HUMIDITY CONTROL SYSTEM

22 AUTO FLIGHT

2200 AUTO FLIGHT SYSTEM
2210 AUTOPILOT SYSTEM
2211 AUTOPILOT COMPUTER
2212 ALTITUDE CONTROLLER
2213 FLIGHT CONTROLLER
2214 AUTOPILOT TRIM INDICATOR
2215 AUTOPILOT MAIN SERVO
2216 AUTOPILOT TRIM SERVO
2220 SPEED-ATTITUDE CORRECT. SYSTEM
2230 AUTO THROTTLE SYSTEM
2250 AERODYNAMIC LOAD ALLEVIATING

23 COMMUNICATIONS

2300 COMMUNICATIONS SYSTEM
2310 HF COMMUNICATION SYSTEM
2311 UHF COMMUNICATION SYSTEM
2312 VHF COMMUNICATION SYSTEM
2320 DATA TRANSMISSION AUTO CALL
2330 ENTERTAINMENT SYSTEM
2340 INTERPHONE & PA SYSTEM
2350 AUDIO INTEGRATING SYSTEM
2360 STATIC DISCHARGE SYSTEM
2370 AUDIO/VIDEO MONITORING

24 ELECTRICAL POWER

2400 ELECTRICAL POWER SYSTEM
2410 ALTERNATOR-GENERATOR DRIVE
2420 AC GENERATION SYSTEM
2421 AC GENERATOR-ALTERNATOR
2422 AC INVERTER
2423 PHASE ADAPTER

24 ELECTRICAL POWER CONT'D

2424 AC REGULATOR
2425 AC INDICATING SYSTEM
2430 DC GENERATING SYSTEM
2431 BATTERY OVERHEAT WARN. SYSTEM
2432 BATTERY/CHARGER SYSTEM
2433 DC RECTIFIER-CONVERTER
2434 DC GENERATOR-ALTERNATOR
2435 STARTER-GENERATOR
2436 DC REGULATOR
2437 DC INDICATING SYSTEM
2440 EXTERNAL POWER SYSTEM
2450 AC POWER DISTRIBUTION SYSTEM
2460 DC POWER/DISTRIBUTION SYSTEM

25 EQUIPMENT/FURNISHINGS

2500 CABIN EQUIPMENT/FURNISHINGS
2510 FLIGHT COMPARTMENT EQUIPMENT
2520 PASSENGER COMPARTMENT EQUIPMENT
2530 BUFFET/GALLEYS
2540 LAVATORIES
2550 CARGO COMPARTMENTS
2551 AGRICULTURAL SPRAY SYSTEM
2560 EMERGENCY EQUIPMENT
2561 LIFE JACKET
2562 EMERGENCY LOCATOR BEACON
2563 PARACHUTE
2564 LIFE RAFT
2565 ESCAPE SLIDE
2570 ACCESSORY COMPARTMENT
2571 BATTERY BOX STRUCTURE
2572 ELECTRONIC SHELF SECTION

26 FIRE PROTECTION

2600 FIRE PROTECTION SYSTEM
2610 DETECTION SYSTEM
2611 SMOKE DETECTION
2612 FIRE DETECTION
2613 OVERHEAT DETECTION
2620 EXTINGUISHING SYSTEM
2621 FIRE BOTTLE, FIXED
2622 FIRE BOTTLE, PORTABLE

27 FLIGHT CONTROLS

2700 FLIGHT CONTROL SYSTEM
2701 CONTROL COLUMN SECTION
2710 AILERON CONTROL SYSTEM
2711 AILERON TAB CONTROL SYSTEM
2720 RUDDER CONTROL SYSTEM
2721 RUDDER TAB CONTROL SYSTEM
2722 RUDDER ACTUATOR
2730 ELEVATOR CONTROL SYSTEM
2731 ELEVATOR TAB CONTROL SYSTEM
2740 STABILIZER CONTROL SYSTEM
2741 STABILIZER POSITION INDICATING
2742 STABILIZER ACTUATOR
2750 TE FLAP CONTROL SYSTEM
2751 TE FLAP POSITION IND. SYSTEM
2752 TE FLAP ACTUATOR
2760 DRAG CONTROL SYSTEM
2761 DRAG CONTROL ACTUATOR
2770 GUST LOCK/DAMPER SYSTEM
2780 LE FLAP CONTROL SYSTEM
2781 LE FLAP POSITION IND. SYSTEM
2782 LE FLAP ACTUATOR

28 FUEL

2800 AIRCRAFT FUEL SYSTEM
2810 FUEL STORAGE
2820 ACFT FUEL DISTRIB. SYSTEM
2821 ACFT FUEL FILTER/STRAINER
2822 FUEL BOOST PUMP
2823 FUEL SELECTOR/SHUTOFF VALVE
2824 FUEL TRANSFER VALVE
2830 FUEL DUMP SYSTEM
2840 ACFT FUEL INDICATING
2841 FUEL QUANTITY INDICATOR
2842 FUEL QUANTITY SENSOR
2843 FUEL TEMPERATURE INDICATING
2844 FUEL PRESSURE INDICATOR

29 HYDRAULIC POWER

2900 HYDRAULIC POWER SYSTEM
2910 HYDRAULIC, MAIN SYSTEM
2911 HYDRAULIC POWER-ACCUMULATOR-MAIN
2912 HYDRAULIC FILTER-MAIN SYSTEM
2913 HYDRAULIC PUMP. ELECT-ENG.-MAIN
2914 HYDRAULIC HANDPUMP-MAIN
2915 HYDRAULIC PRESSURE RELIEF VLV-MAIN
2916 HYDRAULIC RESERVOIR-MAIN
2917 HYDRAULIC PRESSURE REGULATOR-MAIN
2920 HYDRAULIC, AUXILIARY SYSTEM
2921 HYDRAULIC ACCUMULATOR-AUXILIARY
2922 HYDRAULIC FILTER-AUXILIARY
2923 HYDRAULIC PUMP-AUXILIARY
2925 HYDRAULIC PRESSURE RELIEF-AUXILIARY
2926 HYDRAULIC RESERVOIR-AUXILIARY
2927 HYDRAULIC PRESSURE REGULATOR-AUX.
2930 HYDRAULIC SYSTEM INDICATING
2931 HYDRAULIC PRESSURE INDICATOR
2932 HYDRAULIC PRESSURE SENSOR
2933 HYDRAULIC QUANTITY INDICATOR
2934 HYDRAULIC QUANTITY SENSOR

30 ICE AND RAIN PROTECTION

3000 ICE/RAIN PROTECTION SYSTEM
3010 AIRFOIL ANTI/DE-ICE SYSTEM
3020 AIR INTAKE ANTI/DE-ICE SYSTEM
3030 PITOT/STATIC ANTI-ICE SYSTEM
3040 WINDSHIELD/DOOR RAIN/ICE REMOVAL
3050 ANTENNA/RADOME ANTI-ICE/DE-ICE SYSTEM
3060 PROP/ROTOR ANTI-ICE/DE-ICE SYSTEM
3070 WATER LINE ANTI-ICE SYSTEM
3080 ICE DETECTION

31 INSTRUMENTS

3100 INDICATING/RECORDING SYSTEM
3110 INSTRUMENT PANEL
3120 INDEPENDENT INSTRUMENTS (CLOCK, ETC.)
3130 DATA RECORDERS (FLT/MAINT)
3140 CENTRAL COMPUTERS (EICAS)
3150 CENTRAL WARNING
3160 CENTRAL DISPLAY
3170 AUTOMATIC DATA

32 LANDING GEAR

3200 LANDING GEAR SYSTEM
3201 LANDING GEAR/WHEEL FAIRING
3210 MAIN LANDING GEAR
3211 MAIN LANDING GEAR ATTACH SECTION
3212 EMERGENCY FLOTATION SECTION
3213 MAIN LANDING GEAR STRUT/AXLE/TRUCK
3220 NOSE/TAIL LANDING GEAR
3221 NOSE/TAIL LANDING GEAR ATTACH SECTION
3222 NOSE/TAIL LANDING GEAR STRUT/AXLE
3230 LANDING GEAR RETRACT/EXT. SYSTEM
3231 LANDING GEAR DOOR RETRACT SECTION
3232 LANDING GEAR DOOR ACTUATOR
3233 LANDING GEAR ACTUATOR
3234 LANDING GEAR SELECTOR
3240 LANDING GEAR BRAKE SYSTEM
3241 BRAKE ANTI-SKID SECTION
3242 BRAKE
3243 MASTER CYL/BRAKE VALVE
3244 TIRE
3245 TIRE TUBE
3246 WHEEL/SKI/FLOAT
3250 LANDING GEAR STEERING SYSTEM
3251 STEERING UNIT
3252 SHIMMY DAMPER
3260 LANDING GEAR POSITION & WARNING
3270 AUXILIARY GEAR (TAIL SKID)

33 LIGHTS

3300 LIGHTING SYSTEM
3310 FLIGHT COMPARTMENT LIGHTING
3320 PASSENGER COMPARTMENT LIGHTING
3330 CARGO COMPARTMENT LIGHTING
3340 EXTERIOR LIGHTING
3350 EMERGENCY LIGHTING

34 NAVIGATION

3400 NAVIGATION SYSTEM
3410 FLIGHT ENVIRONMENT DATA
3411 PITOT/STATIC SYSTEM
3412 OUTSIDE AIR TEMP. IND./SENSOR
3413 RATE OF CLIMB INDICATOR
3414 AIRSPEED/MACH INDICATING
3415 HIGH SPEED WARNING
3416 ALTIMETER, BAROMETRIC/ENCODER

34 NAVIGATION CONT'D

3417 AIR DATA COMPUTER
3418 STALL WARNING SYSTEM
3420 ATTITUDE AND DIRECTION DATA SYSTEM
3421 ATTITUDE GYRO & IND. SYSTEM
3422 DIRECTIONAL GYRO & IND. SYSTEM
3423 MAGNETIC COMPASS
3424 TURN & BANK/RATE OF TURN INDICATOR
3425 INTEGRATED FLT. DIRECTOR SYSTEM
3430 LANDING & TAXI AIDS
3431 LOCALIZER/VOR SYSTEM
3432 GLIDE SLOPE SYSTEM
3433 MICROWAVE LANDING SYSTEM
3434 MARKER BEACON SYSTEM
3435 HEADS UP DISPLAY SYSTEM
3436 WIND SHEAR DETECTION SYSTEM
3440 INDEPENDENT POS. DETERMINING SYSTEM
3441 INERTIAL GUIDANCE SYSTEM
3442 WEATHER RADAR SYSTEM
3443 DOPPLER SYSTEM
3444 GROUND PROXIMITY SYSTEM
3445 AIR COLLISION AVOIDANCE SYSTEM (TCAS)
3446 NON RADAR WEATHER SYSTEM
3450 DEPENDENT POSITION DETERMINING SYSTEM
3451 DME/TACAN SYSTEM
3452 ATC TRANSPONDER SYSTEM
3453 LORAN SYSTEM
3454 VOR SYSTEM
3455 ADF SYSTEM
3456 OMEGA NAVIGATION SYSTEM
3457 GLOBAL POSITIONING SYSTEM
3460 FLIGHT MANAGE. COMPUTING SYSTEM

35 OXYGEN

3500 OXYGEN SYSTEM
3510 CREW OXYGEN SYSTEM
3520 PASSENGER OXYGEN SYSTEM
3530 PORTABLE OXYGEN SYSTEM

36 PNEUMATIC

3600 PNEUMATIC SYSTEM
3610 PNEUMATIC DISTRIBUTION SYSTEM
3620 PNEUMATIC INDICATING SYSTEM

37 VACUUM

3700 VACUUM SYSTEM
3710 VACUUM DISTRIBUTION SYSTEM
3720 VACUUM INDICATING SYSTEM

38 WATER/WASTE

3800 WATER & WASTE SYSTEM
3810 POTABLE WATER SYSTEM
3820 WASH WATER SYSTEM
3830 WASTE DISPOSAL SYSTEM
3840 AIR SUPPLY (WATER PRESS. SYSTEM)

45 CENTRAL MAINT. SYSTEM

4500 CENTRAL MAINT. COMPUTER

49 AIRBORNE AUXILIARY POWER

4900 AIRBORNE APU SYSTEM
4910 APU COWLING/CONTAINMENT
4920 APU CORE ENGINE
4930 APU ENGINE FUEL & CONTROL
4940 APU START/IGNITION SYSTEM
4950 APU BLEED AIR SYSTEM
4960 APU CONTROLS
4970 APU INDICATING SYSTEM
4980 APU EXHAUST SYSTEM
4990 APU OIL SYSTEM

51 STANDARD PRACTICES/STRUCTURES

5100 STANDARD PRACTICES/STRUCTURES
5101 AIRCRAFT STRUCTURES
5102 BALLOON REPORTS

52 DOORS

5200 DOORS
5210 PASSENGER/CREW DOORS
5220 EMERGENCY EXIT
5230 CARGO/BAGGAGE DOORS
5240 SERVICE DOORS
5241 GALLEY DOORS
5242 E/E COMPARTMENT DOORS
5243 HYDRAULIC COMPARTMENT DOORS
5244 ACCESSORY COMPARTMENT DOORS
5245 AIR CONDITIONING COMPART. DOORS
5246 FLUID SERVICE DOORS

5247 APU DOORS
5248 TAIL CONE DOORS
5250 FIXED INNER DOORS
5260 ENTRANCE STAIRS
5270 DOOR WARNING SYSTEM
5280 LANDING GEAR DOORS

53 FUSELAGE

5300 FUSELAGE STRUCTURE (GENERAL)
5301 AERIAL TOW EQUIPMENT
5302 ROTORCRAFT TAIL BOOM
5310 FUSELAGE MAIN STRUCTURE
5311 FUSELAGE MAIN FRAME
5312 FUSELAGE MAIN BULKHEAD
5313 FUSELAGE MAIN LONGERON/STRINGER
5314 FUSELAGE MAIN KEEL
5315 FUSELAGE MAIN FLOOR BEAM
5320 FUSELAGE MISCELLANEOUS STRUCTURE
5321 FUSELAGE FLOOR PANEL
5322 FUSELAGE INTERNAL MOUNT STRUCTURE
5323 FUSELAGE INTERNAL STAIRS
5324 FUSELAGE FIXED PARTITIONS
5330 FUSELAGE MAIN PLATE/SKIN
5340 FUSELAGE MAIN ATTACH FITTINGS
5341 WING ATTACH FITTINGS (ON FUSELAGE)
5342 STABILIZER ATTACH FITTINGS
5343 LANDING GEAR ATTACH FITTINGS
5344 FUSELAGE DOOR HINGES
5345 FUSELAGE EQUIPMENT ATTACH FITTINGS
5346 POWERPLANT ATTACH FITTINGS
5347 SEAT/CARGO ATTACH FITTINGS
5350 FUSELAGE AERODYNAMIC FAIRINGS

54 NACELLES/PYLONS

5400 NACELLE/PYLON STRUCTURE
5410 MAIN FRAME (ON NACELLE/PYLON)
5411 FRAME/SPAR/RIB(NACELLE/PYLON)
5412 BULKHEAD/FIREWALL (NAC/PYLON)
5413 LONGERON/STRINGER (NAC/PYLON)
5414 PLATE SKIN (NAC/PYLONS)
5415 ATTACH FITTINGS (NAC/PYLON)

55 STABILIZERS

5500 EMPENNAGE STRUCTURE
5510 HORIZONTAL STABILIZER STRUCTURE
5511 HORIZONTAL STABILIZER SPAR/RIB
5512 HORIZONTAL STABILIZER PLATE/SKIN
5513 HORIZONTAL STABILIZER TAB STRUCTURE
5520 ELEVATOR STRUCTURE

55 STABILIZERS CONT'D

5521 ELEVATOR SPAR/RIB STRUCTURE
5522 ELEVATOR PLATES/SKIN STRUCTURE
5523 ELEVATOR TAB STRUCTURE
5530 VERTICAL STABILIZER STRUCTURE
5531 VERTICAL STABILIZER SPAR/RIB STRUCTURE
5532 VERTICAL STABILIZER PLATES/SKIN
5533 VENTRAL STRUCTURE (ON VERT. STAB)
5540 RUDDER STRUCTURE
5541 RUDDER SPAR/RIB STRUCTURE
5542 RUDDER PLATE/SKIN STRUCTURE
5543 RUDDER TAB STRUCTURE
5550 EMPENNAGE FLT. CONT. ATTACH FITTING
5551 HORIZONTAL STABILIZER ATTACH FITTING
5552 ELEVATOR/TAB ATTACH FITTINGS
5553 VERT. STAB. ATTACH FITTINGS
5554 RUDDER/TAB ATTACH FITTINGS

56 WINDOWS

5600 WINDOW/WINDSHIELD SYSTEM
5610 FLIGHT COMPARTMENT WINDOWS
5620 PASSENGER COMPARTMENT WINDOWS
5630 DOOR WINDOWS
5640 INSPECTION WINDOWS

57 WINGS

5700 WING STRUCTURE
5710 WING MAIN FRAME STRUCTURE
5711 WING SPAR STRUCTURE
5712 WING RIB STRUCTURE
5713 WING LONGERON/STRINGER
5714 WING CENTER BOX
5720 WING MISCELLANEOUS STRUCTURE
5730 WING PLATES/SKINS
5740 WING ATTACH FITTINGS
5741 WING, FUSELAGE ATTACH FITTINGS
5742 WING, NAC/PYLON ATTACH FITTINGS
5743 WING, LANDING GEAR ATTACH FITTINGS
5744 CONTROL SURFACE ATTACH FITTINGS
5750 WING CONTROL SURFACE STRUCTURE
5751 AILERON STRUCTURE
5752 AILERON TAB STRUCTURE
5753 TE FLAP STRUCTURE
5754 LEADING EDGE DEVICE STRUCTURE
5755 SPOILER STRUCTURE

61 PROPELLERS/PROPULSORS

6100 PROPELLER SYSTEM
6110 PROPELLER ASSEMBLY
6111 PROPELLER BLADE SECTION
6112 PROPELLER DE-ICE BOOT SECTION
6113 PROPELLER SPINNER SECTION
6114 PROPELLER HUB SECTION
6120 PROPELLER CONTROL SYSTEM
6121 PROPELLER SYNCHRONIZER SECTION
6122 PROPELLER GOVERNOR
6123 PROPELLER FEATHERING/REVERSING
6130 PROPELLER BRAKING
6140 PROPELLER INDICATING SYSTEM

62 MAIN ROTOR

6200 MAIN ROTOR SYSTEM
6210 MAIN ROTOR BLADES
6220 MAIN ROTOR HEAD
6230 MAIN ROTOR MAST/SWASHPLATE
6240 MAIN ROTOR INDICATING SYSTEM

63 MAIN ROTOR DRIVE

6300 MAIN ROTOR DRIVE SYSTEM
6310 ENGINE/TRANSMISSION COUPLING
6320 MAIN ROTOR GEARBOX
6321 MAIN ROTOR BRAKE
6322 ROTORCRAFT COOLING FAN SYSTEM
6330 MAIN ROTOR TRANSMISSION MOUNT
6340 ROTOR DRIVE INDICATING SYSTEM

64 TAIL ROTOR

6400 TAIL ROTOR SYSTEM
6410 TAIL ROTOR BLADE
6420 TAIL ROTOR HEAD
6440 TAIL ROTOR INDICATING SYSTEM

65 TAIL ROTOR DRIVE

6500 TAIL ROTOR DRIVE SYSTEM
6510 TAIL ROTOR DRIVE SHAFT
6520 TAIL ROTOR GEARBOX
6540 TAIL ROTOR DRIVE INDICATING SYSTEM

67 ROTORS FLIGHT CONTROL

6700 ROTORCRAFT FLIGHT CONTROL
6710 MAIN ROTOR CONTROL
6711 TILT ROTOR FLIGHT CONTROL
6720 TAIL ROTOR CONTROL SYSTEM
6730 ROTORCRAFT SERVO SYSTEM

71 POWERPLANT

7100 POWERPLANT SYSTEM
7110 ENGINE COWLING SYSTEM
7111 COWL FLAP SYSTEM
7112 ENGINE AIR BAFFLE SECTION
7120 ENGINE MOUNT SECTION
7130 ENGINE FIRESEALS
7160 ENGINE AIR INTAKE SYSTEM
7170 ENGINE DRAINS

72 TURBINE/TURBOPROP ENGINE

7200 ENGINE (TURBINE/TURBOPROP)
7210 TURBINE ENGINE REDUCTION GEAR
7220 TURBINE ENGINE AIR INLET SECTION
7230 TURBINE ENGINE COMPRESSOR SECTION
7240 TURBINE ENGINE COMBUSTION SECTION
7250 TURBINE SECTION
7260 TURBINE ENGINE ACCESSORY DRIVE
7261 TURBINE ENGINE OIL SYSTEM
7270 TURBINE ENGINE BYPASS SECTION

73 ENGINE FUEL & CONTROL

7300 ENGINE FUEL & CONTROL
7310 ENGINE FUEL DISTRIBUTION
7311 ENGINE FUEL-OIL COOLER
7312 FUEL HEATER
7313 FUEL INJECTOR NOZZLE
7314 ENGINE FUEL PUMP
7320 FUEL CONTROLLING SYSTEM
7321 FUEL CONTROL/ELECTRONIC
7322 FUEL CONTROL/CARBURETOR
7323 TURBINE GOVERNOR
7324 FUEL DIVIDER
7330 ENGINE FUEL INDICATING SYSTEM
7331 FUEL FLOW INDICATING
7332 FUEL PRESSURE INDICATING
7333 FUEL FLOW SENSOR
7334 FUEL PRESSURE SENSOR

74 IGNITION

7400 IGNITION SYSTEM
7410 IGNITION POWER SUPPLY
7411 LOW TENSION COIL
7412 EXCITER
7413 INDUCTION VIBRATOR
7414 MAGNETO/DISTRIBUTOR
7420 IGNITION HARNESS (DISTRIBUTION)
7421 SPARK PLUG/IGNITER
7430 IGNITION SWITCHING

75 AIR

7500 ENGINE BLEED AIR SYSTEM
7510 ENGINE ANTI-ICING SYSTEM
7520 ENGINE COOLING SYSTEM
7530 COMPRESSOR BLEED CONTROL
7531 COMPRESSOR BLEED GOVERNOR
7532 COMPRESSOR BLEED VALVE
7540 BLEED AIR INDICATING SYSTEM

76 ENGINE CONTROLS

7600 ENGINE CONTROLS
7601 ENGINE SYNCHRONIZING
7602 MIXTURE CONTROL
7603 POWER LEVER
7620 ENGINE EMERGENCY SHUTDOWN SYSTEM

77 ENGINE INDICATING

7700 ENGINE INDICATING SYSTEM
7710 POWER INDICATING SYSTEM
7711 ENGINE PRESSURE RATIO (EPR)
7712 ENGINE BMEP/TORQUE INDICATING
7713 MANIFOLD PRESSURE (MP) INDICATING
7714 ENGINE RPM INDICATING SYSTEM
7720 ENGINE TEMP. INDICATING SYSTEM
7721 CYLINDER HEAD TEMP (CHT) INDICATING
7722 ENG. EGT/TIT INDICATING SYSTEM
7730 ENGINE IGNITION ANALYZER SYSTEM
7731 ENGINE IGNITION ANALYZER
7732 ENGINE VIBRATION ANALYZER
7740 ENGINE INTEGRATED INSTRUMENT SYSTEM

78 ENGINE EXHAUST

7800 ENGINE EXHAUST SYSTEM
7810 ENGINE COLLECTOR/TAILOPIPE/NOZZLE
7820 ENGINE NOISE SUPPRESSOR
7830 THRUST REVERSER

79 ENGINE OIL

7900 ENGINE OIL SYSTEM (AIRFRAME)
7910 ENGINE OIL STORAGE (AIRFRAME)
7920 ENGINE OIL DISTRIBUTION (AIRFRAME)
7921 ENGINE OIL COOLER
7922 ENGINE OIL TEMP. REGULATOR
7923 OIL SHUTOFF VALVE
7930 ENGINE OIL INDICATING SYSTEM
7931 ENGINE OIL PRESSURE
7932 ENGINE OIL QUANTITY
7933 ENGINE OIL TEMPERATURE

80 STARTING

8000 ENGINE STARTING SYSTEM
8010 ENGINE CRANKING
8011 ENGINE STARTER
8012 ENGINE START VALVES/CONTROLS

81 TURBOCHARGING

8100 EXHAUST TURBINE SYSTEM (RECIP)
8110 POWER RECOVERY TURBINE (RECIP)
8120 EXHAUST TURBOCHARGER

82 WATER INJECTION

8200 WATER INJECTION SYSTEM

83 ACCESSORY GEARBOXES

8300 ACCESSORY GEARBOXES

85 RECIPROCATING ENGINE

8500 ENGINE (RECIPROCATING)
8510 RECIPROCATING ENGINE FRONT SECTION
8520 RECIPROCATING ENGINE POWER SECTION

8530 RECIPROCATING ENGINE CYLINDER SECTION
8540 RECIPROCATING ENGINE REAR SECTION
8550 RECIPROCATING ENGINE OIL SYSTEM

MECHANICS CREED

UPON MY HONOR I swear that I shall hold in sacred trust the rights and privileges conferred upon me as a certified mechanic. Knowing full well that the safety and lives of others are dependent upon my skill and judgment, I shall never knowingly subject others to risks which I would not be willing to assume for myself, or for those dear to me.

IN DISCHARGING this trust, I pledge myself never to undertake work or approve work which I feel to be beyond the limits of my knowledge; nor shall I allow any non-certificated superior to persuade me to approve aircraft or equipment as airworthy against my better judgment; nor shall I permit my judgment to be influenced by money or other personal gain; nor shall I pass as airworthy aircraft or equipment about which I am in doubt, either as a result of direct inspection or uncertainty regarding the ability of others who have worked on it to accomplish their work satisfactorily.

I REALIZE the grave responsibility which is mine as a certified airman, to exercise my judgment on the airworthiness of aircraft and equipment. I, therefore, pledge unyielding adherence to these precepts for the advancement of aviation and for the dignity of my vocation.